

ము. గణము;

For perusal	<i>[Signature]</i>
Secretary	
Member/T	
Member/F	
Chairman	

శ్రీయుత గౌరవనీయులైన కార్యదర్శి  
తలంగాణ రాష్ట్ర విద్యుత్తు నియంత్రణమండలి.

తమిళ వ్యతిరేక గౌరవ కమిషన్ కు  
విన్నవించు కొనునది.

విషయము :- 2017-18 ఆర్థిక సంవత్సరము కొరకు  
విద్యుత్తు, ARR లై మరయు రెగ్యులేటరీ పై  
అభ్యంతరాలు - నలమల సమర్పించుట గురించి.

నాకు బహుశంగ విచారణలో మాట్లాడుటకు అవకాశము  
ఇవ్వగలరని ప్రార్థన. గౌ. అ. ద. పం. ల లో

TSERC, HYDERABAD  
INWARD  
15 MAY 2017  
509  
Signature  
No.

సమస్యలు 1. ఏ సూచనలకు సంబంధించి ప్రణాళిక  
నెంచుకొనుట/వసువుల తీర్మానం నెంచుకొనుట  
పాంపు, పాంపు వాటి సమాఖ్య సులభమైనది -  
తీర్మానం నెంచుకొనుట అంటే వాటి పంపుల అంతరాల  
పై తోచిన వివరాలు తెలుపుచున్న అక్షరాలు  
అంతరాల అంతరాల పంపుల తీర్మానము.  
అంతరాల వలన ఏకాగ్రతను వింగిల్ల  
తీర్మానం నెంచుకొనుట అంటే వాటి పంపుల అంతరాల  
పై తోచిన వివరాలు తెలుపుచున్న అక్షరాలు

2. సమస్యలను వలన కలుగుతున్న అసౌకర్యాలను  
సమస్యలను వలన కలుగుతున్న అసౌకర్యాలను  
తమిళభీయము

చినిపతి TSSPDCL ✓  
TSNPDEL, కు పంపిస్తానది.

సంకేతము :- MRRM.  
వీరు :- M. SPIDHAR RAO  
గృహం :- 504, Pasipathi Residency,  
మండలం :- 2-1-174, 175  
జిల్లా :- Nallakunta  
PIN CODE :- 500044  
MOBILENO :- 9866381090

1. ప్రభుత్వం సర్వేయం చేసిన 3- మోటార్ల పరిధిలోని విద్యుత్తు, (బస్, మానా, 2.50 ఎకరాల స్టేషన్లు) వంటివి ఉంటే ఈ క్రింది విధిలో వర్తించు- ఆ పరిధిలోని విద్యుత్తు మరియు 12 సం||ల విద్యుత్ సరఫరా పట్లూ వీటికి 24 సం||ల విద్యుత్ సరఫరా వ్యయం - అధికారమును, క్రొవ్వును చేయాలి గాన రివెన్యూ మరియు పీసీసీ ల వ్యా (పెండ్లి) మరియు పీసీసీ లకు ప్రైవేటులు; ప్రైవేటు అంటే మాంస కర్షణలుగా ఉంటే అందుకు తగు ఫీజు మరియు ఖాతా పాస్ పోస్టు అంటే తగు ఫీజు ఉంటుంది. (ప్రైవేటు కంపెనీల విద్యుత్ సరఫరా పట్లూ వీటికి తగు వ్యా (పెండ్లి) మరియు DISCOM వాటి కర్షణలు మరియు పీసీసీ లకు.

2. TSSPDCL లోని C.G.R.F మరియు TSNPDCL లోని ముందర దాఖలు, C.G.R.F ల సమస్యలు; నిబంధనలు; అందుకు సంబంధించిన విషయాలపై పరిష్కారాలు (క్రియాశీలకంగా ఉండేవి) గాన. వాటి గాన రివెన్యూ మరియు పీసీసీ ల మరియు వాటి వ్యయ క్షేత్ర కర్షణలు తెలుపుతూ ఉంటే C.G.R.F ల విషయాలకు సంబంధించిన (ప్రైవేటు) మరియు కర్షణలు గాన C.G.R.F ల (క్రియాశీలకంగా ఉండేవి) వాటి వాటి వ్యా (పెండ్లి) మరియు పీసీసీ ల మరియు వాటి వ్యయ క్షేత్ర కర్షణలు తెలుపుతూ ఉంటే C.G.R.F లకు సంబంధించిన విషయాలపై నిబంధనలు గాన వ్యా (పెండ్లి) మరియు వాటి వ్యా (పెండ్లి) మరియు వాటి వ్యయ క్షేత్ర కర్షణలు తెలుపుతూ ఉంటే.







14. ఎలక్ట్రిక్ కేబుల్ మార్కెట్ లో సమాధాన (ఎక్స్‌టెన్షన్) త్వర సమయం తీసుకోవడానికి అవకాశం కల్పించాలి. సేత 2 సంవత్సరాల పాటు, ముఖ్యంగా గ్రామీణ ప్రాంతాలలో, త్వర సమయం తీసుకోవడానికి అవకాశం కల్పించాలి. త్వర సమయం తీసుకోవడానికి అవకాశం కల్పించాలి. త్వర సమయం తీసుకోవడానికి అవకాశం కల్పించాలి. త్వర సమయం తీసుకోవడానికి అవకాశం కల్పించాలి.

15. AP ERC రిజల్యూషన్ - 4 - 2013 లో ఎవరినీ DTR వేరే తీసుకోవడానికి అవకాశం కల్పించాలి. DTR త్వర సమయం తీసుకోవడానికి అవకాశం కల్పించాలి. త్వర సమయం తీసుకోవడానికి అవకాశం కల్పించాలి. త్వర సమయం తీసుకోవడానికి అవకాశం కల్పించాలి. త్వర సమయం తీసుకోవడానికి అవకాశం కల్పించాలి. త్వర సమయం తీసుకోవడానికి అవకాశం కల్పించాలి.

NORTHERN POWER DISTRIBUTION COMPANY OF TELANGANA LIMITED  
OPERATION CIRCLE, NIZAMABAD

Human electrical accidents occurred during the financial year 2015-16

Sl. No.	Date and time of accident	Day/ Night	Division	Constituency	Particular of the deceased including his profession etc.	Place of accident with full details such as Village, Mandal, Section, Sub-division & Division of NPDCL	Cr.No.& Section of Law, Date of FIR & Police station	Age	Sex	Dept./ Non-Dept.	Fatal / Non-Fatal	Cause of accident	Amount in Rs.	Remarks	Proposals Submitted D.No. & Date	Sanctioned/ Rejected
1	01-04-2015 14:00 hrs	Day	Kamareddy	Kamareddy	Katroth Chander, S/o. Devla, R/o. Gundaram(V), Tadwai (Sec.)	SS-III, Yellareddypally	FIR No.40/2015, dt.01-04-2015	32	Male	Non-Dept.	Fatal	The casualty replacing the HG fuses un-authorisedly and opened the 11 KV AB switch but 1 set of male & female contact is not opened and touched the live wire got electricuted and died on the spot.	200000		Exgratia proposal submitted vide ref D.No.2274/15, Dt:04.02.16	Sanctioned by CGM(OP) vide sanction No.04/2016-17 & D.No.25/16, Dt.04-04-2016
2	07-05-2015, 17:45 Hrs	Night	Kamareddy	Yellareddy	Thota Ramesh S/o Ashaiah R/o S.S.Reddy(V), Lingampet(S)	S.S.Reddy(V), Lingampet(S)	FIR.61/2015, Dt.08-05-2015 U/S.174 CRPC	22	Male	Non-Dept.	Fatal	While the victim came knowing the supply timings at 33/11 KV SS S.S.Reddy, unfortunately accidentally, came in contact with snapped live conductor wire got electrocuted and injured and died in the hospital.	200000	1) Remarks copy communicated DE(O)KMR D.No.2452/15, Dt:18.02.15	1) Exgratia proposals submitted vide D.No.2182/15, Dt:25.01.16, & 2)Exgratia proposals re-submitted to the CGM/OP/Wgl vide D.No.65/16, dt:13-04-2016	Sanctioned by CGM(OP) vide sanction No.19/2016-17 & D.No.371/16, Dt.18-0-2016.
3	10-05-2015, 22:45 Hrs	Night	Banswada	Banswada	Somanagari Ravinder S/o Bhoomalaiah R/o Banswada(V) & (M)	Banswada(V) & (M)	FIR.107/2007, Dt.11-05-2015 U/S.174 CRPC	28	Male	Non-Dept.	Fatal	While the victim is going to upstairs of house, unfortunately he touches the 11 KV line and electrocuted, died on the spot	200000	1) Letter received from Dist.Collector for clarification of exgratia payment 2) CGM remarks communcd D.No.1558/15, Dt: 24.11.15	1) Exgratia proposals submitted D.no /15, Dt: 2) Re-Sub vide D.No:2800/15, dt.21-03-2016 3) Re-sub vide D.No./16, Dt.-01-2017 (Humanity grounds)	2) Sanction No.65/16 D.No.2840/16, Dt.18-17. 1) Rejected by CGM(OP) vide D.No.100/16, Dt.18-0-2016 (No departmental fault)
4	27-05-2015 14:10 hrs	Day	Armoor	Balkonda	Sri Thalla Chinna Gangadhar, S/o. Pedda Gangaram, R/o. Chengal(V)	Pachala Nadukuda(V)	FIR.59/2015, Dt.27-05-2015 PS: Velpur	35	Male	Non-Dept.	Fatal	The victim which he climbed the single DP and sitting on the 11 KV AB switch of DTR, he touched the R.p.h. With his hand to connect to 11 KV AB switch he received electric shock & fallen on the ground & died on the spot.		1) Remarks called from DE(O)ARM vide D.No.1552/15, Dt:21-11-2015. 2) Letter received from Dist.Collector for clarification of exgratia payment. 3) All reports called from DE vide D.No.2455/16, Dt.20-17.	D.No.,/17, Dt.-04-2017.	
5	01-06-2015 18:30 hours	Night	Kamareddy	Kamareddy	Sri Shaik@Dudjekula Ahmed, S/o. Hussain, R/o. Lingapur(V), Kamareddy(R) (Sec.)	Near SS-33, 15 KVA DTR at Lingapur(V)	FIR No.99/15, dt.02-06-2015	25	Male	Non-Dept.	Fatal	While decorating the Grama Panchayath building with lights, the electric main wire accidentally contacted to his head, he sustained electric shock and fell from the building immediately he was shifted to Govt. area hospital. Kamareddy and doctor declared that he was died.	200000		1) Exgratia proposal submitted Vide D.No.2219/15, Dt:29.01.16 2) Re-sub D.No.1728/16, Dt.02-11-2016.	Sanction No.59/16-17 & D.No.2836/16-17, Dt.18-1-17 Rejected by CGM(OP) vide D.No.1095/16, Dt.28-03-2016 (No departmental fault)

Date and time of accident	Day/ Night	Division	Constituency	Particular of the deceased including his profession etc.	Place of accident with full details such as Village, Mandal, Section, Sub-division & Division of NPDCI	Cr.No. & Section of Law, Date of FIR & Police station	Age	Sex	Dept./ Non-Dept.	Fatal / Non-Fatal	Cosue of accident	Amount in Rs.	Remarks	Proposals Submitted D.No. & Date	Sanctioned/ Reje.
6	16-06-2015, 21:50 Hrs	Night	Nizamabad	Nizamabad Rural	Nannipally Kannaiah S/o Thirupathi R/o Sarangapur(V), Nizamabad (M)	Sarangapur(V), Nizamabad (M)	.....	37	Male	Non-Dept.	Non-Fatal		Reports not received	Proposal submitted	Rejected (Non fatal accident case, not eligible for exgratia)
7	24-06-2015, 15:00 Hrs	Day	Nizamabad	Nizamabad Town	Pabba Suresh Kumar S/o Limbadri, Nizamabad	Dept SPM, Nizamabad	.....	.....	Male	Dept.	Non-Fatal		Reports not received		Rejected (Non fatal accident case, not eligible for exgratia)
8	29-06-2015, 10:00 Hrs	Day	Nizamabad	Nizamabad Rural	Vannedas S/o Gangaram, Yanampally(V), Bardipur(M)	Yanampally(V), Bardipur(M)	.....	35	Male	Non-Dept.	Non-Fatal		Reports not received	Proposal submitted	Rejected (Non fatal accident case, not eligible for exgratia)
9	03-07-2015, 07:00 Hrs	Day	Banswada	Banswada	Smt.Soankamlema Bai W/o Goutham, Sompur(V), Kotagiri(M)	Sompur(V), Kotagiri(M)	.....	25	Female	Non-Dept.	Non-Fatal		Reports not received	Proposal submitted	Rejected (Non fatal accident case, not eligible for exgratia)
10	03-07-2015, 10:30 Hrs	Day	Kamareddy	Kamareddy	B.Yellaiah(AM/Laxmidewanpally) S/o Balalah, H.No. 101, Bhiknour(N) &(M)	SS-6/2x25KVA DTR's Laxmidewanpally(V), Bhiknour(N) Section	.....	54	Male	Dept. ALM	Non-Fatal		Reports not received		Rejected (Non fatal accident case, not eligible for exgratia)
11	11-07-2015, 20:40 hrs	Night	Banswada	Jukkal	Sri Kammari Nagesh, S/o. Kammari Shankar, Kowlas(V), Jukkal(S)	Kowlas(V), Jukkal (Mdl)	FIR No.35/2015, dt.12-07-2015	55	Male	Non-Dept.	Fatal	200000		Exgratia proposal submitted to CGM(O)Wgl vide ref D.No.2337/15, Dt:07.02.16	Sanctioned by CGM(OP) vide sanction No.03/2016-17 & D.No.28/16, Dt.04-04-2016.
12	26-07-2015 09:00 Hrs	Day	Nizamabad	Armoor	Loka Narsareddy, S/o. Loka Rajanna, R/o Noothpally(V), Nandipet(M)	Noothpally(V) & (S), Nandipet(M)	FIR No.123/15, Date: 26-07-2015	43	Male	Non-Dept.	Fatal	200000	1) Accident due to consumer side fault	1)D.No. 1121/15-16, dt:14.09.15 2) Re-sub D.No.2321/15, Dt:5.02.16 3) Re-sub Vide D.No./16, Dt.-01-2017 (Humanity grounds).	Sancton No.64/16-1 & D.No.2835/16-17, Dt.18-1-17 {Rejected by CGM(OP) vide D.No.236/16, Dt.03-05-2016 (No departmental fault)}
13	02-08-2015 16:10 Hrs	Day	Nizamabad	Nizamabad Rural	Buddala Mohan S/o Rajaiiah, R/o Gollapally(V), Dichpally(S)	SS-101, 100 KVA, Nadipally	.....	35	Male	Non-Dept.	Fatal		Detailed report called Vide D.No.1830/15, Dt:23.12.15		
14	03-08-2015 21:00 Hrs	Night	Armoor	Balkonda	Banavath Bhuma Naik S/o Lacha, Velgathoor Thanda, Mupkal(S), Balkonda(M)	11KV Line near SS-177, 16 KVA DTR	.....	65	Male	Non-Dept.	Fatal		Detailed report called Vide D.no.1829/15, Dt:23.12.15		
15	03-08-2015, 21:10 hrs	Day	Armoor	Balkonda	Sri Dhooma Naik, S/o. Lachha, Velgathoor(V)	SS-177/16 KVA DTR at Velgathoor(V)	FIR.127/2015, Dt.4-8-15 174 Cr.PC Balkonda PS	65	Male	Non-Dept.	Fatal		Reports received on 28-09-2015 & Returned to DE(O)ARR vide D.No.1299/15, Dt:01-10-2015		



Date and time of accident	Day/ Night	Division	Constituency	Particular of the deceased including his profession etc.	Place of accident with full details such as Village, Mandal, Section, Sub-division & Division of NPDC	Cr.No.& Section of Law, Date of FIR & Police station	Age	Sex	Dept./ Non-Dept.	Fatal / Non-Fatal	Casue of accident	Amount in Rs.	Remarks	Proposals Submitted D.No. & Date	Sanctioned/ Reject	
16	07-08-2015 14:30 Hrs	Day	Nizamabad	Nizamabad Urban	B.Ravi Kumar S/o Shanker, JLM(Contract), D-IV/Nizamabad Town.	NL-01, near Padmashali Sangam, D-IV/ Nizamabad.	.....	33	Male	Dept. JLM(Contract)	Non-Fatal		While Clearing the tree branches at location NL-01, near Padmashali Sangam, the JLM suddenly fallen on the ground and injured.	Reports not received		
17	08-08-2015 09:00 Hrs	Day	Nizamabad	Nizamabad Rural	Banoth Ramesh S/o Tarasingh R/o Dharmaram(V), Nizamabad(M)	SS-61, 16 KVA, Dharmaram-M(V)	.....	24	Male	Non-Dept	Fatal	200000	Un-authorisedly replacement of HG fuses on SS-61/16 KVA DTR at Dharmaram-M(V) got electrocuted died on spot.	Exgratia proposal submitted Vide D.No.2243/15, Dt:01.02.16	Sanctioned by CGM(OP) vide sanct No.02/2016-17 & D.No.24/16, Dt.04-2016.	
18	09-08-2015, 09:30 hrs	Day	Kamareddy	Kamareddy	Kcm. Ileni Pooja, D/o. Bikshapathi Rao, R/o. Velpugonda(V)	SS-04/100 KVA, Velpugonda(V)	FIR.118/2015, Dt.9-8-15	18	Female	Non-Dept.	Fatal	200000	The victim has plucking flowers in front of her house. Due to rain in the morning hours, the existing service wire snapped was supported with damaged GI wire which is touched to the LT line to plants. Hence she is electrocuted, died on the spot.	1) Exgratia proposal submitted Vide D.No.2172/15, Dt:23.01.16 2) Resubmitted (WHIP) D.No.2356/16, Dt.10-01-2017.	Sanction No.61/16 & D.No.2832/16-1 Dt.18-1-17 {Rejected by CGM(C vide D.No.1040/1 Dt.22-03-2016 (No departmenta fault))	
19	23-08-2015 15:30 Hrs	Day	Nizamabad	Nizamabad Urban	Menatkar Satish S/o Shanker, D-III/ Nizamabad Town.	D-III/Nizamabad Town	.....	17	Male	Non-Dept.	Fatal		Due to his family problems he touched to LT line and died.	Detailed report called Vide D.No.1823/15, Dt:23.12.2015		
20	23-08-2015 21:00 Hrs	Day	Kamareddy	Yellareddy	Gunoeboina Narsimlu S/o Balrajaiah, R/o Nagireddypet(V) & (M)	SS-73/63 KVA DTR, Nagireddypet(V)	FIR No.76/2015, dt.24-08-2015 174 Cr PC Nagireddypet	50	Male	Non-Dept.	Fatal		The victim for protecting his cane and paddy arranged electrical fencing suddenly he touched the fencing got electrocuted and spot died.	Accident due to consumer side fault.	Reports submitted (ATS, PR & DR) Vide D.No.2218/15, Dt:29.01.16	
21	02-09-2015 8:00 hrs	Day	Kamareddy	Yellareddy	Mudam Sailoo, S/o. Balaiah, R/o. Lingampet(V) & Section	SS-13, Lingampet	FIR No.104/2015, dt.02-09-2015	28	Male	Non-Dept.	Fatal	200000	The victim had gone to his bore well on SS-13, while repairing starter box of the motor touched service wire, accidentally got electric shock and died on the spot.	1) Exgratia proposal submitted Vide D.No.2544/15, Dt:02.03.16 2) Re-sub D.No.2209/16, Dt.22-12-16. (Humanitarian grounds)	Sanction No.58/15- & D.No.2841/16-1 Dt.18-1-17. {Rejected by CGM(C vide D.No. 1025/16 Dt.21-03-2016 (No Dept. fault))	
22	13-09-2015	Day	Banswada	Jukkal	Kurme Ramgonda R/o Allapur(V), Pitlam(S) & (M)	Allapur(V), Pitlam(S) & (M)		38	Male	Non-Dept.	Fatal		Reports called from DE(O)KMR vide D.No.1396/15, Dt:17-10-2015			
23	21-09-2015 17:15 hrs	Day	Nizamabad	Bodhan	Kankala Gangaram, S/o. Abbalah, H.No.3-6/1, Bardipur(V), Bodhan(M)	Bardipur(V), Bodhan(M)	FIR.317/2015, Dt.22-09-2015 U/S.174 CRPC	35	Male	Non-Dept.	Fatal	200000	While lifting the failed borewell motor from the borewell underneath of HT line with iron pipes of 20 feet length, due to sudden unbalance of lifted pipe touched the 11 KV line got electrocuted, died on the spot.	1) Letter received from Dist.Collector for clarification of exgratia payment. 2) Re-sub vide D.No./16, Dt.-01-0217 (Humanity grounds).	Sanction No.63/16- & D.No.2834/16, Dt 1-17 {Rejected by CGM(C vide D.No.42/16, Dt. 04-2016 (No Dept. Fault))	
24	25-09-2015 08:30 hrs	Day	Armoor	Armoor	Arepally Chinna Narsalah S/o Nadpi Bojanna R/o Pipri(V), Armoor(M)	Pipri(V), Armoor(M)	FIR.347/2015, Dt.25-09-2015 U/S.174 CRPC Armoor PS	31	Male	Non-Dept.	Fatal		While the victim unauthorisedly hooking near LT line for his decorative lights suddenly he got electrocuted and injured and died in hospital.	Form-A received from DE(O)/ARR on 15-10-2015.		

Date and time of accident	Day/ Night	Division	Constituency	Particular of the deceased including his profession etc.	Place of accident with full details such as Village, Mandal, Section, Sub-division & Division of NPDCL	Cr.No.& Section of Law, Date of FIR & Police station	Age	Sex	Dept./ Non-Deptl.	Fatal / Non-Fatal	Case of accident	Amount in Rs.	Remarks	Proposals Submitted D.No. & Date	Sanctioned/ Rejected
25 28-09-2015 17:30 hrs	Day	Kamareddy	Kamareddy	Sri Amgoth Venu Prasad, S/o. Bansilal, R/o. Lethamamidi Thanda, Gundaram(V) in Tadwai section	SS-10, Lethamamidi Thanda	FIR.117/2015, Dt.29-09-2015	20	Male	Non-Dept.	Fatal	The casualty replacing the HG fuse un-authorisedly and opening AB switch, 1 No. contact was not opened and supply extended to the DTR, got electrocuted and died on the spot.	200000		Proposal submitted vide D.No. 638/16, Dt.18-06-16.	Sanctioned by CGM(OP) vide sanction No.25/2016-17 & D.No.916/16, Dt.12-07-2016.
26 30-09-2015 8:00 hrs	Day	Banswada	Banswada	Kum. Bhairawar Anitha, D/c. Bhairawar Prabhu, R/o. Shakkarga Big (V)	1-71, Shakkarga Big(V)	FIR No.91/2015, Dt.30-09-2015 PS: Madnoor	12	Female	Non-Dept.	Fatal	The victim tried to collect firewood at top of the house, when she touched to slab iron rods, the electricity supply was passed from damaged service wire cable through slab iron rods to her body got electrocuted and died.			D.No.1869/16, Dt.16-11-2016	Returned by CGM(OP) vide D.No.2166/16, Dt.28-11-2016. (Dept.not responsible for accident)
27 15-10-2015 11:30 hrs	Day	Armoor	Nizamabad Rural	P.Chiranjeevi, JLM-C/Op/Manoharabad, Jakranpally(M)	Kolipak Village, Janranpally(M)	....	32	Male	Dept.	Non-Fatal	While attending for connecting 11KV jumper near SS-24/100KVA he was fallen on the ground from pole by breaking of back clamp of 11KV V-xarm on 11KV kolipak Ag-I feeder and he got injuries at his feet.		PR received from ADE(O)Armoor		
28 17-10-2015 16:45 hrs	Day	Nizamabad	Bodhan	Sri.Ramesh C/o Bana Sailoo R/o Waddepally(V)	SS-3, Waddepally(V)	....	22	Male	Non-Dept.	Non-Fatal			Detailed report called vide D.no.1831/15, Dt:23.12.15		
29 17-10-2015 14:30 hrs	Day	Banswada	Banswada	Sri.Mettu Shiva Kumar S/o Krishna R/o Banswada	Banswada Bidi Workers Colony	FIR.272/2015, Dt.18-10-2015 U/S.174 CRPC	35	Male	Non-Dept.	Fatal	While the victim unauthorisedly hooking near LT line for using iron rod got electrocuted and spot died.	200000	1) Detailed report called vide D.No.1821/15, Dt:23.12.15	1) Exgratia proposals submitted vide D.No.2620/15, Dt:04.03.16, 2) Re-sub vide D.No./16, Dt.-01-2017 (Humanity grounds)	Sanction No.66/16-17 & D.No.2838/16-17, Dt 18-1-17 (Rejected by CGM(OP) vide D.No.81/16, Dt.1:04-2016 (No deptl. fault))
30 27-10-2015 10:25 hrs	Day	Nizamabad	Armoor	Sri.Chelimeela Gangadhar S/o Bojanna R/o Vannel(K), Noothpally(S)	SS-26 & 27/2x25 KVA, Vannel(K), Noothpally(S)	....	30	Male	Non-Dept.	Fatal	Due to the body shock motor supply to borewell iron pipe and he touched to pipe for water and got electrocuted and spot died.		Reports not received		
31 31-10-2015	Day	Kamareddy	Yellareddy	Sri.Bonagiri Koti S/o Pentaiah R/o Reddypally(V), Medak Dist.	Akkampally Cheruvu at Thandur(V)		35	Male	Non-Dept.	Non-Fatal	Victim standing on Lorry cabin for loading of tree branches touches the 11kV Thandur feeder got electrocuted and injured.		Detailed report called vide D.No.1820/15, Dt:23.12.15		
32 26-11-2015 18:00 hrs to 19:00 hrs	Day	Kamareddy	Yellareddy	Kammari Pandari, S/o. Lingaiah, R/o Rudraram	Near SS-08/63 KVA DTR, Rudraram(V)	FIP. No.176/2015, Dt.27-11-2015	32	Male	Non-Dept.	Fatal	The victim want to rig another bore well, for this purpose want to stop the power supply to LT line of SS-08/63 KVA DTR, un-authorisedly opened the AB switch & climbed the DTR for removal of 11 KV HG fuses, 1 No. AB switch blade not opened and the casualty got electrocuted and died on the spot.	200000	Remarks called from CGM(OP) vide D.No.221/16, Dt.02-05-2016 vide Endt.No.395/16, dt.19-05-2016.	1) Exgratia proposal D.No.63/16, Dt:13.04.16 2) Re-sub. Vide D.No.796/16, Dt.12-7-16.	Sanctioned by CGM(OP) vide sanction No.29/2016-17 & D.No.1081/16, Dt.28-2016.

No.	Date and time of accident	Day/ Night	Division	Constituency	Particulars of the deceased including his profession etc.	full details such as Village, Mandal, Section, Sub-division & Division of NPDC	of Law, Date of FIR & Police station	Age	Sex	Dept./ Non-Dept.	Fatal / Non-Fatal	Casue of accident	Amount in Rs.	Remarks	Proposals Submitted D.No. & Date	Sanctioned/ Reject
33	30-11-2015 10:00 hrs	Day	Banswada	Banswada	Sri Puppala Sailoo, S/o. Late Lingam, R/o. Hegdoli(V), Kotagiri Sec.	Sy.No.178/E/2, Hegdoli(V)	FIR No.161/2015, Dt.30-11-2015	35	Male	Non-Dept.	Fatal	The victim was cutting the paddy with Harvester, when he is try to up the conductor with stick, touch the live conductor, electrocuted and died on the spot.	200000		1) Exgratia proposals submitted to the CGM/OP/Wgl vide D.No.2799/15, dt.21-03-2016 2) Re-sub vide D.No./16, Dt.-01-2017 (Humanity grounds).	Sanction No.67/16 & D.No.2837/16-1 Dt.18-1-17 (Rejected by CGM) vide D.No.51/16, Dt.04-2016 (No deptl. Fault)
34	04-12-2015 09:00 hrs	Day	Nizamabad	Nizamabad Rural	Sri Nunavath Babu, S/o Dhupya, R/o Malkapoor(M) thanda, Sarangapoor(S)	Near SS-122/25KVA DTR Malkapoor M Thanda	--	43	Male	Non-Dept.	Fatal	The casualty went to agriculture land of Sri Nunavath prabhu, S/o Dhupya to paddy seen. Sri Nunavath prabhu, S/o Dhupya provide fencing with electricity to protect his land from wild animals which is not known Sri Nunavath Babu and got electrocuted and spot dead.		Detailed report called from DE/NZB vide D.No.2639/15, Dt.10.03.16		
35	16-12-2015 19:30 hrs	Night	Nizamabad	Bodhan	Sri Tenugu S. Gangadhar, S/o Gangaram, R/o Binola(v), Navipet (M & S)	SS-46/25 KVA DTR, Binola(V)	FIR No.152/15, Dt.17-12-2015	52	Male	Non-Dept.	Fatal	The victim hiraself worked his bore well starter box on his land. He has got electric shock, injurcd his body and shifted to arca civil hospital, on the way he was died	200000	Remarks called, D.No.298 /16, Dt. 07-05-16.	1) Exgratia proposal submitted D.No.574/16, Dt: 14.06.2016 2) Re-sub vide D.No./16, Dt.-01-2017 (Humanity grounds).	Sanction No.62/16 & D.No.2833/16-1 Dt.18-1-17 (Rejected by CGM) vide D.No.787/1 Dt.27-06-2016. (No deptl. Fault)
36	29-01-2016 06-42 hrs	Day	Nizamabad	Bodhan	Sri Begari Sailoo, S/o. Lalaiah, R/o. Bhavanipet(V), Bodhan(M)	SS-42, 43 & 44			Male	Non-Dept.	Non-Fatal	The victim who is having domestic problems and health problems was gone and climbed the DTR plintn and intentionally captured the incoming jumper and got electric shock and fell down. Leter he was taken to hospita! Nizamabad for treatment.		1) Form-A received from ADE(O)/Bodhan on 09-02-2016. 2) All reports called for vide D.No.1128/16, Dt.12 -08-16.		
37	31-01-2016 14:30 hrs	Day	Nizamabad	Armoor	Sri Bingi Ramulu, S/o. Poshanna, R/o. Badguna	33/11 KV Badguna sub-station yard	FIR No.15/2016, Dt.31-01-2016 U/s: 174 Cr.Pc	55	Male	Non-Dept.	Fatal	After pouring the water to earth pits of the power transformer, he went out to gate of yard and fell down and he was died.	500000	Detailed report called from DE(O)nzv vide D.No. 2364/15, Dt:12.02.2016	1) Proposa D.No.569/16, dt.13-06-2016 2) DR called D.No.824/16, Dt.30-06-16. 3) Re-sub D.No./16, Dt.-10-16. 4) Re-sub D.No.1560/16, Dt.17-10-2016.	Sanction No.E0/11 & D.No.2839/16- Dt.18-1-17 (Rejected by CGM) vide D.No.1096/ Dt.29-07-2016 (No deptl. Fault)
38	05-02-2016 04:25 hrs	Day	Nizamabad	Bodhar.	Goguloth Rekya Naik, S/o. Hemla Naik, R/o. Bellal farm(V), Bodhar.(M)	SS-3, 1x100 KVA		53	Male	Non Dept.	Non-Fatal	The victim himself who gone to SS-3 Bellal for replacing the HG fuse and AB switch opened but not observed properly about whether all the phases opened or not and climbed the structure got shock and severe burns at face and legs and fell down near the structure. He was shifted to Govt.Hospital, Bodha for treatment.		1) Form-A received from ADE(O)/Bodhan on 09-02-2016. 2) All reports called for vide D.No.1128/16, Dt.12 -08-16.		



NORTHERN POWER DISTRIBUTION COMPANY OF TELANGANA LIMITED  
OPERATION CIRCLE, NIZAMABAD

Human electrical accidents occurred during the financial year 2016-17

Sl. No.	Date and time of accident	Day/ Night	Division	Constituency	Particular of the deceased including his profession etc.	Place of accident	Cr.No. & Section of Law, Date of FIR & Police station	Age	Sex	Dept./ Non-Dept.	Fatal / Non-Fatal	Casue of accident	ATS no.	Amount in Rs.	Remarks	Proposals Submitted D.No. & Date	Sanctioned/ Rejected
1	04-04-2016 10:30 hrs	Day	Kamareddy	Kamareddy	Sri Narla Sailoo, S/o. Pochaiiah, R/o. Lingareddypet(V)	House of Sri A. Cyandra Shekar in Yellareddy(T)	FIR No.34/2016, Dt.14-04-2016.	27	Male	Non-Dept.	Fatal	The victim was working for house construction work, he got contacted with nearby 33 KV Nagireddypet (high voltage) line and got severe burns and shifted to CHC, Yellareddy for treatment. After first aid treatment the casualty was shifted to Gandhi Hospital, Secunderabad for further treatment upto 13-04-2016 and died on the same day at about 23:00 hours.		400000	---	D.No.476/16, Dt.25-05-2016.	Sanctioned No.21/2016-17 & D.No.789/16, Dt.27-06-2016.
2	07-04-2016 01 am to 05 pm	Night	Kamareddy	Kamareddy	Unknown Male person	SS-285(100 KVA)DTR at Govt. Civil Hospital, Kamareddy		-	Male	Non-Dept.	Fatal				Reports not received		
3	21-04-2016 13:00 hrs	Day	Banswada	Banswada	Sri Pothuraju Sailoo, S/o. Peeraiah, Age: 25 years at Birkur(V) & section	Birkur	FIR No.50/2016, Dt.21-04-2016.	25	Male	Non-Dept.	Fatal	The victim replacing street lights using aluminium ladder, balance out and the ladder fallen on 11 KV Birkur-MHQ feeder and died on the spot.		400000	---	D.No.650/16, Dt.22-06-2016.	Sanctioned No.26/2016-17 & D.No.915/16, Dt.12-07-2016.
4	28-04-2016 12:00 hrs	Day	Nizamabad	Bodhan	Sri Sormar Chinna Linganna S/o Pothanna, R/o Lingapur	SS-9/63 KVA Lingapoor		52	Male	Non-Dept.	Fatal	While repairing his agl damaged service wire electrocuted and died on spot.			Reports not received		
5	04-05-2016 18:30 hrs	Day	Kamareddy	Kamareddy	Sri D. Rama Swamy, S/o. Bhurmalai, R/o Seri Bibipet(V) in Bibipet section	SS-01/100 KVA DTR at Seri Bibipet	FIR No.8/2016, Dt.05-05-2016 PS: Bibipet	37	Male	Non-Dept.	Fatal	Due to heavy gale and wind tree branches are fell down on the LT line of SS-01 of Seri Bibipet, while removing the tree branches along with ALM Sri.Raja Narsu. Back feeding supply is entered from the Medak District supply which are using double supply by the consumer, the supply is entered through electrical wire and he is electrocuted he is shifted to hospital but on the way he is expired.		400000		D.No.1821/16, Dt.11-11-16	Sanctioned No.46/2016-17 & D.No.2172/16, Dt.28-11-2016.
6	15-05-2016 03:00	Night	Kamareddy	Kamareddy	Smt. Savugu Lachavva, W/o Narsalah, Age:65 yrs, R/o Sar,jameshwar(V)	In Hut, at Sangameshwar(V) Domakonda(S)		65	Female	Non-Dept.	Fatal	When sleeping human being in the hut in the mid night at 03 hrs(as per local enquiry) the hut was got fired and human being burnt on the spot. At the time of inspection it is found that she was no authorised service connection at the spot of incident. There was no electricity line near to the Hut.			---	1) paper clipping report submitted to CGM(O) vide D.No.794/16, DT:12-07-2016 (preliminary report & sketch)	

Date and time of accident	Day/ Night	Division	Constituency	Particular of the deceased including his profession etc.	Place of accident	Cr. No. & Section of Law, Date of FIR & Police station	Age	Sex	Dept./ Non-Dept.	Fatal / Non-Fatal	Cause of accident	ATS no.	Amount in Rs.	Remarks	Proposals Submitted D.No. & Date	Sanctioned/ Rejected
22-05-2016 08:30 hrs	Day	Armoor	Armoor	Sri Akula Pedda Gangaram, S/o. Gangaram at Mamidipally(V) in Perkt section	Mamidipally(V)	40/2016, Dt.22-5-16 174 CrPC Jakranpally	60	Male	Non-Dept.	Fatal	The SC.No.827/V Brahmanpally(V) is connected from SS-16/100 KVA DTR at Mamidipally(V) and extended with support of fencing wire to the Agl. land of Sy.No.144/1 of Brahmanpally(V) and the service wire having joint in middle and insulation of joint is damaged, touched to the fencing, the victim has touched the fencing wire while crossing agl. field, got electrocuted and died on the spot.			1) All reports are not received and returned vide D.No. /16, Dt. -7-16.	D.No.1785/16, Dt.09-11-2016	Returned vide D.No.2084/16, Dt.23-11-2016. (Dept.not responsible for accident)
25-05-2016 14:45 hrs	Day	Armoor	Balkonda	Sri Jangam. Srinivas S/o Gangaram R/o Ithwarpet, Balkonda(M)	SS-12/15 KVA DTR, Ithwarpet		32	Male	Non-Dept.	Fatal	While stringing of diss cable wire illegally at SS-12/15 KVA DTR at Ithwarpet(V), accidentally touched the S-phase HG fuse set got electricuted and died on the spot.			Reports not received		
26-05-2016 16:00 hrs	Day	Kamareddy	Yellareddy	Sri Dhanani Bala Mallalah @Bala Mailu, S/o. Balalah, R/o Konnapally(V) in Lingampet(M &S)	11 KV Pothalpally	FIR No.51/2016, Dt.26-05-2016 PS: Lingampet	23	Male	Non-Dept.	Fatal	The victim cutting tree branches for his sheeps/goats, unfortunately tree branches leaned on 11KV line, current passing through tree branches to him got electrocuted and died on the spot.				D.No.1571/16, Dt.18-10-2016.	Returned vide D.No.2036/16, Dt.16-11-2016. (Dept.not responsible for accident)
29-05-2016 17:30 hrs	Day	Nizamabad	Nizamabad Rural	Sri Manga Satish S/o Narayana R/o Manchippa	SS-16/100 KVA, Manchippa		27	Male	Non-Dept.	Non-Fatal	While trying to un-authorized fuse off call on SS-16/100 KVA lighting DTR at Manchippa, touched to near by 11KV Manchippa Agl feeder got electricuted and burn injuries to hand and neck.			Reports not received		
29-05-2016 08:15 hrs	Day	Armoor	Balkonda	Sri.K. Jannari Rajanna P/o Bheemgal			50	Male	Non-Dept.	Fatal				Reports not received		
03-06-2016 07:00 hrs	Day	Nizamabad	Nizamabad Rural	Sri Mallenarthi Prasad (Age: 16 years), S/o. E. humalah, R/o. Nyallal(V)	Near SS-214/16 KVA, Sirpur, Nizamabad rural section	FIR No.195/16, Dt.6-6-16 PS: NCB (R)	16	Male	Non-Dept.	Fatal	The victim went near LT AB cable of SS-214/16 KVA DTR at Sirpur(V) with sheeps. Due to heavy gale & wind, the LT AB cable come down to ground level and the victim left up the LT AB cable with hands to pass his sheeps, got electrocuted and died on the spot.	001450	400000	1) Reports received on 9-11-16.	D.No.1917/16, Dt.21-11-16	Sanctioned No.50/16-17 & D.No.2573/16, Dt.21-12-2016.
07-06-2016 14:10	Day	Nizamabad	Armoor	Sri Katroth Gangadhar, S/o Rukmal, R/o Abbapoor(B)	on 11KV Chikli Agl feeder	FIR No.65/2016, Dt.07-06-2016. Makloor	25	Male	Non-Dept.	Fatal	Due to breakdown of 11 KV Chikli Agl. feeder the LC was taken at 13:20 hrs and while attending the breakdown one additional phase at particular point of accident 11 KV Chikli town phase not taken any LC, and touched the phase electrocuted, fell down and shifted to hospital on the way he was died.				D.No.1132/16, Dt. 12-08-2016.	Rejected vide D.No.1304/16, Dt.27-08-16 that, FIR booked under section 304-A-IPC is not eligible and intimated to DF-NZB vide SE Lr. D.No.1387/16, Dt.20-09-16.

Date and time of accident	Day/ Night	Division	Constituency	Particular of the deceased including his profession etc.	Place of accident	Cr.No. & Section of Law, Date of FIR & Police station	Age	Sex	Dept./ Non-Dept.	Fatal / Non-Fatal	Cause of accident	ATS no.	Amount in Rs.	Remarks	Proposals Submitted D.No. & Date	Sanctioned/ Rejected
14 12-06-2016 18:05 hrs	Night	Banswada	Banswada	Sri Gayini Arun, S/o. G. Sailoo, R/o. Mosra(V), Chandur Sec.	Laxmapur(V)	FIR No.112/2016, Dt.13-06-2016. PS: Varsi	27	Male	Non-Dept.	Fatal	The Line Men of Mosra distribution has taken Line clear on 11KV Malkapur feeder vide LC No.004384 at 11:20 Hrs for connecting the jumpers of damaged poles line on that feeder. The Line clear has returned at 18:05 Hrs. At the same time inter poles work was executed by M/s Anil Electricals on the feeder. Due to misunderstanding between the Line Man and Gang Leader at the time of test charge of the feeder the deceased was on the line got electrocuted and died at hospital after first aid.				D.No.1444/16, Dt. 28-09-2016.	Rejected vide D.No.1747/16, Dt.19-10-16 that, FIR booked under section 304-A-IPC is not eligible and intimated to DE-NZB vide SE Lr. D.No.1662/16, Dt.26-10-16.
15 19-06-2016 21:34 hrs	Night	Nizamabad	Bodhan	Sri Uppu Bhumalah, S/o Poshetty, R/o Yedpally	SS-68, 25KVA, Yedpally	FIR.No.92/2016, Dt.20-06-2016, Yedapally PS	32	Male	Non-Dept.	Fatal	At SS-68/25 KVA DTR the 11 KV AB switch opened and Y-phase HG fuse found blown. The victim without informing departmental staff himself opened the AB switch and tried to renew the HG fuse, at that time raining due to lightning humming the victim afraid off and slipped and fallen on the earth pipe, his head was injured and died on the spot. At 33/11 KVSS Yedapally no trippings on the connected 11 KV Jaithapoor feeder.	001156	400000	1) Only Form-A (ATS No.001156) received. 2) All Reports called from DE(O) vide D.No.1121/16, Dt.12-08-16.	D.No.2493/16, Dt.-2501-2017	Sanctioned No.93/16-17 & D.No.3067/16, Dt.16-02-2017.
16 21-06-2016 6:30 hrs	Day	Banswada	Banswada	Sri Kottam Sailu, S/o. Kottam Narsaiah, R/o. Birkur(V) & section	Birkur(V)	FIR No.80/16, Dt.21-06-16, Birkur P.S.	38	Male	Non-Dept.	Fatal	While replacing the damaged incoming service wire in wet area, the victim tried to joint live service wire without any safeguard, got electrocuted and died on the spot.	001703	400000	Detailed report called for	1) D.No.1963/16, Dt.25-11-16 2) Re-sub. D.No.2211/16, Dt.22-12-2016 (Humanitarian grounds).	2) Sanction No.69/16 & D.No.2856/16, Dt.19-11-17 1) Returned vide D.No.2265/16, Dt.17-12-16 (Dept.not responsible)
17 22-06-2016	Day	Nizamabad	Nizamabad Urban	Sri Middle Ramesh, S/o. Middle Laxman, H.Nr. 6-88/58/3, Aryanagar, D-IV/Nizamabad(T)		FIR No.124/16, Dt.23-06-16, Town-IV/NZB PS		Male	Non-Dept.	Fatal				Detailed report called for		
18 29-06-2016 17:00	Day	Nizamabad	Bodhan	Sri More Kiran, S/o More Ramchander, R/o Achanpally, Bodhan(T1) Sec.	LT line of SS-5,100KVA Pandufarm	FIR No.220/16, Dt.30-06-16, Bodhan PS	20	Male	Non-Dept.	Fatal	The victim bringing the grass from field on motor cycle and returned with grass, while crossing the LT line (one phase) coming from SS-V (100 KVA DTR) Achanpally snapped and fallen on him, got electrocuted and died on the spot.	001197	400000	1) Only Form-A (ATS No.001197) received. 2) All Reports called from DE(O) vide D.No.1121/16, Dt.12-08-16.	D.No.2486/16, Dt.25-01-2017	Sanction No.99/16 & D.No.3134/16, Dt.25-02-2017
19 05-07-2016 14:00 hrs	Day	Kamareddy	Nizamabad	Smt. Darshanala Rekha, W/o. Shivaraju R/o Abangapatnam(V) in Navireti(S)	Abangapatnam	FIR No.R1/2016, Dt.06-07-2016, PS:Navireti	60	Female	Non-Dept.	Fatal	The GI wire was tagged from building to neem tree and the deceased was put the wet clothes on GI wire for drying and got electrocuted and dead on the spot.	001637			D.No.1619/16, Dt.19-10-2016.	Returned vide D.No.1966/16, Dt.4-11-16 (No deptl. fault)

Date and time of accident	Day/ Night	Division	Constituency	Particular of the deceased including his profession etc.	Place of accident	Cr.No. & Section of Law, Date of FIR & Police station	Age	Sex	Dept./ Non-Dept.	Fatal / Non-Fatal	Casue of accident	ATS no.	Amount in Rs.	Remarks	Proposals Submitted D.No. & Date	Sanctioned/ Rejected	
20	11-07-2016 16:00	Day	Nizamabad	Bodhan	Sri.Munawar Subhash S/o Devarao R/o Thaggelly. Bodhan(M)	Shanker Reddy, 25 KVA DTR		25	Male	Non-Dept.	Fatal	11 KV Kaldurki feeder at Consumer side Starter box. Reports as follows.			Reports not received		
21	16-07-2016 17:00 hrs	Day	Banswada	Banswada	Sri Mctri Gangonda, S/o. Metri Berugonda, R/o. Barangedgi(V)	Field, Barangedgi(V)	FIR No.104/16 Dt.17-07-16 PS: Birkoor	33	Male	Non-Dept.	Fatal	While the victim tried to replace fuses in the motor starter box, got electrocuted and died on the spot. The spot was covered with wet.	001709	400000		1) D.No.1962/16, Dt.25-11-16 2) Re-sub. D.No.2210/16, Dt.22-12-2016. (Humanitarian grounds)	2) Sanction No.70/16 & D.No.2855/16, Dt.19-01-2017 1) Returned vide D.No.2257/16, Dt.06-12-16 (Dept.not responsible)
22	21-07-2016 10:30 hrs	Day	Kamareddy		Sri Naikote Mahesh Kumar, S/o. Chandraiah, R/o. Malthummedha(V)	SS-13/100 KVA	FIR.No.64/2016, Dt.21-07-2016, Nagireddypet PS	25	Male	Non-Dept.	Fatal	The victim observed that, his Agl. bore motor is not working and he went to SS-13/100 KVA DTR Malthummedha for switching off the LT breaker for checking his bore motor then he returned to start the LT breaker, unfortunately touched the 11 KV bush rod, got electrocuted and died on the spot.	001880	400000		D.No.2507/16, Dt.27-01-2017	Sanction No.89/16 & D.No.3059/16, Dt.16-02-17.
23	22-07-2016 7:00 hrs	Day	Armoor	Armoor	Sri Singireddy Yellaiah, S/o. Singireddy Narsaiah, R/o. Chimanpally	Chimanpally	1-91, 55-53 Chimanpally	60	Male	Non-Dept.	Fatal	The SC.No.155, Cat-V, Chimanpally(V) is connected from SS-53/100 KVA DTR and the service wire having No.of joints from pole to starter box and the deceased was accidentally touched the jointing place of service wire, got electrocuted and died on the spot.	001682		PRE.DR received on 20-12-16 D.No.765/16, Dt.17-12-16.	D.No.2060/16, Dt.05-12-2016.	Returned vide D.No.2329/16, Dt.19-12-16 (Dept. not responsible)
24	26-07-2016 21:00 hrs	Night	Banswada	Banswada	Sri Ehoorna Ramesh (Age: 26 years), S/o. Laxmaiah, R/o. Komalancha(V)	Kornalancha	FIR No.134/16 Dt.27-07-16 PS: Nizamsagar	26	Male	Non-Dept.	Fatal	In the agriculture field the consumer has tested the supply with by putting tester on live 11KV middle bush rod, got electrocuted and died on the spot.	001601			D.No.1967/16, Dt.25-11-16	Returned vide D.No.2282/16, Dt.8-12-16 (Dept. not responsible)
25	28-07-2016 09:00 hrs	Day	Armoor		Sri Basa Mahender, S/o. Mallaiat, R/o Donkal(V) In Murchad sec	Donkal	FIR.No.124/2016, Dt.28-07-2016, Murchad PS		Male	Non-Dept.	Fatal	The service wire which is passing from starter to motor insulation is damaged and touched to the motor, the victim while cutting the grass suddenly touched to the motor, got electrocuted and died on the spot.	001345	400000		D.No.2571/16, Dt.31-01-2017	Sanction No.97/16 & D.No.3097/16, Dt.21-02-17.
26	30-07-2016 11:30 hrs	Day	Kamareddy		Sri Kotha Kummari Raju, S/o. Narayana, R/o. Bhavanipet Thanda In Machareddy section	Komatikunta	FIR.No.120/2016, Dt.30-07-2016, Machareddy PS	35	Male	Non-Dept.	Fatal	The Victim Sri Kotha Kummari Raju, S/o. Narayana has went for measuring mission Kakathya works at Komati Kunta Chervu Katta with very long iron scale. While he measuring chervu katta length with long iron scale, scale was touched to the 11 KV line and died on spot.	001824	400000	D.No.2572/16, Dt.31-01-2017 (Cause not clear)	D.No.3069/16, Dt.21-03-2017.	Sanction No.08/17 & D.No.91/17, Dt.13-04-17.
27	06-08-2016 17:30 hrs	Day	Nizamabad	Bodhan	Sri Satapuram Abbaiah, S/o. Laxmaiah, R/o. Mangalpad, Yedapally Sec.	SS-02 Improvement 25 KVA DTR	FIR No.140/16, Dt.08-08-16 PS: Yedpally (33 / IPC)	35	Male	Non-Dept.	Fatal	The victim doing LT extension work underneath of 11 KV existing line, suddenly he got hamming and fell down, gone under treatment and died on 11-08-2016.	001503		Reports not received	D.No.1556/16, Dt. 17-10-2016.	Returned vide D.No.1952/16, Dt.4-11-16 (337 IPC is not eligible)



Date and time of accident	Day/ Night	Division	Constituency	Particular of the deceased including his profession etc.	Place of accident	Cr.No.& Section of Law, Date of FIR & Police station	Age	Sex	Dept./ Non-Dept.	Fatal / Non-Fatal	Cause of accident	ATS no.	Amount in Rs.	Remarks	Proposals Submitted D.No. & Date	Sanctioned/ Rejected
28 12-08-2016 14:30 hrs	Day	Kamareddy	Kamareddy	Sri Gaddam Pochaiah, S/o. Siddaiah, R/o. Malkapur(V)	Near SS-005/100 KVA at Malkapur(V)		-	Male	Non-Dept.	Fatal	The deceased removing the motor from his bore well GI pipes touched the 6.3 KV line got electrocuted and died on the spot.			Only PR, Form of Elec.accidents & Sketch received on 19-9-16.	1) PR, DR, sketch vide D.No.1446/16, Dt. 28-09-2016. 2) Other all reports vide D.No.1838/16, Dt.15-11-16.	Returned vide D.No.2126/16, Dt.23-11-2016. (Dept.not responsible for accident)
29 13-08-2016 16:45 hrs	Day	Armoor	Balkonda	Sri Uggeera Sayanna, S/o. Poshanna, R/o. Palem(V)	Palem(V)	FIR No.161/16 Dt.13-08-16 PS: Morthad	51	Male	Non-Dept.	Fatal	The victim went to field of Sri Bodolla Rajanna, S/o. Chinniah for cutting the grass unexpectedly he also cut the service wire, got electrocuted and died on the spot.	001425		Returned by CGM D.No.2330/16, Dt.19-12-16.	1) D.No.2058/16, Dt.05-12-2016. 2) D.No./17, Dt.-04-2017.	Returned vide D.No.2330/16, Dt.19-12-2016. (Dept.not responsible)
30 23-08-2016 15:30 hrs	Day	Nizamabad	Nizamabad Rural	Sri Mothe Mallaiiah, S/o. Mothe Pd. Rajanna, R/o. Rampur(V), Dichpally Sec.	SS-180/25 KVA, Rampur(V)		60	Male	Non-Dept.	Fatal	The consumer motor body shock and dead.		400000	1) Reports not received 2) Returned vide D.No.2413/16, Dt.17-01-17 (Photo enclosed)	D.No.3023/16, Dt.-18-03-2017	Sanction No.07/17 & D.No.98/17, Dt.13-04-17.
31 23-08-2016 19:35 hrs	Night	Kamareddy	Kamareddy	Sri Boreddy Ramulu, S/o. Muthaiah, Domakonda(V)	SS-24/100 KVA, Pole-28 at Domakonda		55	Male	Non-Dept.	Fatal	The deceased provided supply through GI wire to his maize surrounding for safe guard the crops from the pigs, when he went to the field during night hours he came in contact with the live GI wire got electrocuted and died on the spot.				1) Form-A, PR & Sketch Vide D.No.1494/16, Dt: 03.10.16. 2) Other all report vide D.No.1839/16, Dt.15-11-16.	Returned vide D.No.2083/16, Dt.23-11-2016. (Dept.not responsible for accident)
32 07-09-2016 11:30 hrs	Day	Nizamabad	Nizamabad Urban	Sri Pili Srikanth, S/o. Prasad, R/o. Kenjar(V), Nizamabad(R) Sec.			20	Male	Non-Dept.	Fatal				TM received on 07-09-2016.		
33 07-09-2016 10:30 hrs	Day	Kamareddy	Kamareddy	Sri Neela Naveen Kumar, S/o. Bhumaiiah, R/o. Bhiknoor(V) & Sec.,	SS-01/100 KVA DTR at Bhiknoor(V)			Male	Non-Dept.	Fatal	While extending supply to the Ganesh pandal un-authorisedly by hooking from nearby LT line got electrocuted and died on the spot.			TM received on 09-09-2016.	Reports D.No.1573/16, Dt.18-10-2016.	No deptl. fault.
34 13-09-2016 02:00 hrs	Night	Kamareddy	Kamareddy	Sri Ireni Vivek, S/o. Veeraiah, R/o. Domakonda(V) & Sec.	SS-48/100 KVA DTR at Domakonda		17	Male	Non-Dept.	Fatal	The deceased hooking the wires to the over head line, first he provided phase wire, after providing phase wire, he rectifying the neutral wire to the wooden stick, he came in contact with the line phase wire electric shock occurred and shifted to the hospital, died in the hospital.			1) TM received on 14-09-2016.	1) Reports D.No.1574/16, Dt.18-10-2016. 2) Proposal D.No.1783/16, Dt.09-11-16.	Returned vide D.No.2164/16, Dt.28-11-2016. (Dept.not responsible for accident)
35 15-09-2016 22:30 hrs	Night	Armoor		Sri Malavath Shekar S/o. Laxman R/o Sunket(V)		FIR.No.181/2016, Dt.16-09-2016, Morthad PS		Male	Non-Dept.	Fatal	The wire used for music system which was connected through plug in switch board. While Ganapathi shobha yatra is going on the Malavath Shekar is touched the wire where the wire insulation failed and he got electrocuted and died on the spot.	001521	400000		D.No.2570/16, Dt.31-01-2017	Sanction No.98/16 & D.No.3096/16, Dt.21-02-17.

Date and time of accident	Day/ Night	Division	Constituency	Particulars of the deceased including his profession etc.	Place of accident	Cr.No. & Section of Law, Date of FIR & Police station	Age	Sex	Dept./ Non-Dept.	Fatal / Non-Fatal	Cause of accident	ATS no.	Amount in Rs.	Remarks	Proposals Submitted D.No. & Date	Sanctioned/ Rejected
16-09-2016	Day	Nizamabad	Nizamabad	Sri M. Naveen Kumar, S/o. M. Narayana, H.No.5-11-827, Yellamagutta, Nizamabad	D-II/NZB	FIR No.211/16 Dt.16-09-16 PS:Town-IV/NZB		Male	Non-Dept.	Fatal				1) All reports called vide D.No.2711/16, Dt.14-02-2017. 2) FIR, Sketch, Report received vide D.No.750/16, Dt.13-3-17.		
18-09-2016 18:30 hrs	Day	Kamareddy		Sri Maloch Savairam, S/o. Valya, R/o. Wajjappally(V)	Wajjappally	FIR No.123/16 Dt.19-09-16 PS: Gandhari	43	Male	Non-Dept.	Fatal	The victim went to the DTR and he saw HG fuse blown. After that without giving any information to the departmental persons he himself opened AB switch to provide the HG fuse. Accidentally he got electrocuted and died on the spot.	001725	400000	All reports called vide D.No.2711/16, Dt.14-02-2017.	D.No.2473/16, Dt.23-01-2017.	Sanction No.107/16 & D.No.3200/16, Dt.09-03-17.
20-09-2016 14:10 hrs	Day	Nizamabad	Bodhan	Sri Sriram Ramulu, S/o. Sriram Mallalah, R/o. Bardipur(V), Bodhar,(R) Sec.			64	Male	Non-Dept.	Fatal				TM received on 20-09-2016.		
21-09-2016 12:25 HRS	Day	Kamareddy	Kamareddy	Sri Balla Shekar, S/o. Vittal			34	Male	Deptl.	Non-Fatal				TM received on 21-09-2016.		
21-09-2016 20:30 HRS	Night	Nizamabad	Nizamabad(R)	Sri Dhaki Narsaiah, S/o. Late Pochaiiah, Sirnapally(V), Dharpally Sec.			45	Male	Non-Dept.	Fatal	Sri Pogula Pedda Gangaram, S/o. Gangaram is un-authorisedly using power supply for fencing of his Agl. land to protect from wild animals and the victim passed over the fencing wire, got electrocuted and died on the spot.	001790	400000	1) TM received on 22-09-2016. 2) PR & Received on 31-10-16 3) All reports called vide D.No.2129/16, Dt.14-12-2016.	D.No.2488/16, Dt.25-01-2017.	Sanctioned No.90/16-17 & D.No.3060/16, Dt.16-02-2017.
27-09-2016 10:00 hrs	Day	Nizamabad	Nizamabad	Sri Thokala Babanna, S/o. Gangaram, R/o. Kaloor(V), Sarangapur section	SS-49/25 KVA DTR, Kaloor(V)	FIR No.362, Dt.28-09-16, NZB Rural PS	46	Male	Non-Dept.	Fatal	The victim went to his agriculture land by passing LT line of SS-49/25 KVA DTR of Kaloor(V), during night hours the LT line come down from X-Arm due to gale and wind, got contact, electrocuted and died on the spot.	001687	400000	ATS, PR, DR & sketch received on 10-11-16 & returned for all reports vide D.No./16, Dt.-11-16.	D.No.1954/16, Dt.23-11-2016.	Sanction No.49/16-17 & D.No.2574/16, Dt.21-12-2016.
02-10-2016 06.00 hrs	Day	Kamareddy	Yellareddy	Sri Katrothi Lalsingh, S/o. Vasuram, R/o. Shetpally Sangareddy(V)	SS-57/25 KVA DTR Shetpally Sangareddy	FIR.No.148/2016, Dt.02-10-2016, PS: Lingampet	46	Male	Non-Dept.	Fatal	The victim went to his agricultural field and put his legs on insulation damaged service wire, got electrocuted and died on the spot.	001963			D.No.2847/16, Dt.28-02-2017.	
06-10-2016 11:00 hrs	Day	Armoor		Sri Mittapally Chinna Rajeshwar, S/o. Bhunamaana, R/o. Dharmora(V)	Dharmora	FIR.No199/2016, Dt.07-10-2016, Morthad PS	55	Male	Non-Dept.	Fatal	After removing of jumpers, the failure transformer moved for transport in bullock cart by the concerned Lineman Sri Jagathi and supporting consumers suddenly the transformer skipped and fallen on the victim and injured and shifted by consumers to Nizamabad hospital for treatment, during the treatment he is died at 17:30 hours on the same day.	No ATS	400000		D.No.2492/16, Dt.25-01-2017	Sanction No.106/16 & D.No.3179/16, Dt. -03-2017.

Date and time of accident	Day/ Night	Division	Constituency	Particular of the deceased including his profession etc.	Place of accident	Cr.No.& Section of Law, Date of FIR & Police station	Age	Sex	Dept./ Non-Dept.	Fatal / Non-Fatal	Cause of accident	ATS no.	Amount in Rs.	Remarks	Proposals Submitted D.No. & Date	Sanctioned/ Rejected
09-10-2016 18:00 hrs	Day	Kamareddy	Yellareddy	Sri Banoth Gangya, S/o. Badya, R/o. Rampoor(V)	SS-01/63 KVA DTR, Rampoor Thanda	FIR.No.138/2016, Dt.09-10-2016, PS: Yellareddy	57	Male	Non-Dept.	Fatal	The victim went to his agricultural field, the LT line of SS-07/63 KVA DTR Rampoor Thanda which was snapped and fallen in the agriculture field and touched live LT line, got electrocuted and died on the spot.	001969	400000		D.No.2860/16, Dt.28-02-2017.	Sanction No.127/16-17 & D.No.3403/16, Dt.28-03-2017.
12-10-2016 09:30 hrs	Day	Nizamabad	Bodhan	Borgam Krishna, S/o. Sailu, Yedapally(V)	Mangalpad Chowrasta		42	Male	Non-Dept.	Fatal	While procession of Durga Matha idol kept in a tractor with self generator is going on at about 23:00 hrs nearer to Mangalpad Chowrasta, the victim who was also participated in the procession is tried to take Prasadam he felt sudden shock and fell down. Immediately he was shifted to Govt. Hospital Bodhan, from there to Nizamabad for better treatment while going he was died at 01:20 AM on 13-10-16. At 33/11 KVSS, Yedapally there was no trippings on 11 KV town feeder breaker. The fellow who was given Prasadam to the victim has not get any shock or humming. It may be due to generator supply discrepancy the humming might have came. Due to the humming of generator the victim psychologically got effected and fell down.	001817		PR&DR received vide D.No.1947/16, Dt.19-01-16.	D.No./16, Dt.-03-2017 (PR&DR Sent)	
17-10-2016 12:40 hrs	Day	Nizamabad		Sri Neredla Chinna Balaiah, S/o. Sambalah, R/o. Mylaram(V)	SS-06/63 KVA DTR at Mylaram	FIR.No.118/2016, Dt.17-10-2016, Dharpally PS	45	Male	Non-Dept.	Fatal	The victim went to his agricultural bore well (SC.No.42, Cat-V) and touched the motor body and got shock due to body shock motor and died on the spot.	001804	400000	1) PR Received on 31-10-16 2) All reports called vide D.No.2130/16, Dt.14-12-2016.	D.No.2778/16, Dt.23-02-2017.	Sanction No.116/16 & D.No.3322/16, Dt.21-03-2017.
23-10-2016, 11:00 hrs	Day	Kamareddy	Kamareddy	Sri Pachanti Chinna Rajaiah, S/o. Poshaiyah, R/o. Siddapoor(V)	Siddapoor(V)	FIR.No.155/2016, Dt.23-10-2016, PS: Tadiwai	30	Male	Non-Dept.	Fatal	The victim went to his agricultural fields for channeling the water, while starting the motor, accidentally got contacted with live parts in the starter, got electrocuted and died on the spot.	001976	400000		D.No.2849/16, Dt.28-02-2017.	Sanction No.155/16 & D.No.3321/16, Dt.21-03-2017.
25-10-2016 08:30 hrs	Day	Nizamabad	Bodhan	Sri Mekolawar Gangadhar, S/o Ganapathi, R/o. ARP Camp in Renjal section	Near Renjal		48	Male	Non-Dept.	Fatal	The victim who is hamali worker has gone (sitting on the top of the lorry cabin) along with lorry No.AP01 6462, when lorry reached near Renjal(V) the driver want to take turn on the road, lorry gone nearer to 11 KV line passing near by and got touched and died on the spot.	001671		1) All reports called vide D.No.2131/16, Dt.14-12-2016. 2) All reports called D.No.2707/16, Dt.13-02-2017 (Only PR&DR Received)		

Date and time of accident	Day/ Night	Division	Constituency	Particular of the deceased including his profession etc.	Place of accident	Cr.No.& Section of Law, Date of FIR & Police station	Age	Sex	Dept./ Non-Dept.	Fatal / Non-Fatal	Cause of accident	ATS no.	Amount in Rs.	Remarks	Proposals Submitted D.No. & Date	Sanctioned/ Rejected	
49	03-11-2016 21:00 hrs	Night	Kamareddy	Kamareddy	Sri Lantbadi Dhoopsingh @ Guguloth Dhoopsingh, S/o. Guguloth Beelya, R/o. Lethamamidi Thanda, Gundaram(V)	SS-06/100 KVA DTR, Gundaram	FIR No.162/2016, Dt.04-11-2016, PS: Tadwai	43	Male	Non-Dept.	Fatal	The victim went to his agricultural field and observed that his bore well motor is not working, suspecting the DTR Y-phase HG fuse solid core insulator is failed and the same was replaced with plastic pipe vertically which was binded to the HG fuse channel using as HG fuse and ignorantly done binding upto the support channel. After closing the AB switch the supply extended upto the AB switch handle, got electrocuted and died on the spot	001973		D.No.2864/16, Dt.28-02-2017 (Rectifying report)		
50	07-11-2016	Day	Nizamabad	Dichpally	Sri B. Sajan Kumar, S/o. Venkatesham, JLM/OP/ Mittapally in Dichpally Sec.			Male	Deptl.	Fatal				Detailed report called vide D.No.2454/16, Dt.20-1-2017.			
51	16-11-2016 14:00 hrs	Day	Nizamabad		Sri Komere Srinivas, S/o. Malliah, R/o. Suddulam(V)	SS-42/25 KVA, Suddulam(V)		25	Male	Non-Dept.	Fatal	The victim trying to catch the fish with electric shock, hence he run nearly 300 meters of service wire from SS-42/25 KVA DTR un-authorisedly and provide power supply in water, by mistake he fallen in the water, got electrocuted and died on the spot.			1) PR received on 24-11-2016. 2) All reports called vide D.No.2137/16, Dt.15-12-2016.		
52	25-11-2016 12:15 hrs	Day	Banswada	Banswada	Golla Sai Kumar, S/o. Kistiah, R/o. Chinna Nagaram(V)	Near Nallaralla DTR, Nagaram.	FIR No.428/16, Dt.25-11-16 PS: Banswada	17	Male	Non-Dept.	Fatal	While the victim tried to erect inter pole at his agriculture field, the iron rod has come out from the pole and contact with 11 KV line, got electrocuted and died on the spot.	001826	400000		D.No.2358/16, Dt.11-01-2017.	Sanction No.75/16-17 & D.No.2924/16, Dt.28-01-2017.
53	03-12-2016 6:30 hrs	Day	Nizamabad	Nizamabad	Sri Ullenga Chinna Sailoo, S/o. Sailoo, R/o. Manchippa(V), NZB (R) Sec.	SS-06/63 KVA, Manchippa(V)		42	Male	Non-Dept.	Fatal	The victim climbed SS-06/63 KVA DTR structure without intimating to departmental staff to remove his Agl. service wire which is connected on it, got electric shock and then admitted to hospital for treatment and died in the hospital.			Only PR received, All reports called vide D.No.2252/16, Dt.24-12-2016.	D.No.02/17, Dt.04-04-2017.	
54	30-12-2016 10:30 hrs	Day	Banswada		Sri Bheemanpalli Pavindar, S/o. B. Kistiah, R/o. Maqdumpur(V)	Maqdumpur	FIR.No.207/2016, Dt.30-12-2016, Nizamsagar PS	26	Male	Non-Dept.	Fatal	The victim climbed the pole by switch off the existing 15 KVA DTR on SS-18 without taking any 11 KV L/C, but the existing line was HT/LT (6.3 KV line/LT line) for giving new GP RWS motor un-authorisedly to the LT work, he touched the 6.3 KV line, got electrocuted and died on the spot.	001898	400000		D.No.2677/16, Dt.10-02-2016.	Sanction No.108/16 & D.No.3199/16, Dt.09-03-2017.

16-17 est 54 - 22 Pay. 2 Rogatal = 30 - Pandinigi 9 Retnara -

**NORTHERN POWER DISTRIBUTION COMPANY OF TELANGANA LIMITED**  
**OPERATION CIRCLE, NIZAMABAD**  
**Animals electrical accidents occurred during the financial year 2015-16**

Sl. No.	Date and time of accident	Division	Sub-Division	Section	Day/Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Cause of accident	Remarks	Proposal submitted	Sanctioned/Rejected
1	13-04-2015 06:30 hrs	Nizamabad	Nizamabad(R)	Dichpally	Day	1 No. she buffalo	Sri Peggarla Sailoo, S/o. Narsimloo, R/o. kamalapur(V)	Kamalapur	20,000	The return supply passed to the earth pipe due to heavy gale & wind the LT 3 ph. Agl. 7 hours line jumper hanged and touched LT AB cable 24 hours neutral conductor at the same time buffalo touched the earth pipe, electrocuted and died on the spot.	1) No ATS, the same remarks communicated by CGM(OP) vide D.No.1086/15, Dt.23-06-16. 2) Remarks attended by DE vide D.No.275/16, Dt.01-06-16.	Proposals submitted vide D.No.582/16, Dt.14-06-16.	Sanctioned vide sanction No.62/2016-17 and D.No.910/16, Dt.12-07-2016.
2	15-05-2015 10:00 hrs	Nizamabad	Nandipet	Navipet	Day	1 No. she buffalo	Sri Buka Salbaba, S/o. Narsaiah, R/o. Abhangapatnam(V)	SS-08/25 KVA DTR at Mahantham(V)	20,000	While she buffalo grazing the grass near SS-08/25 KVA DTR, touched to 11 KV HT bush got electrocuted and died on the spot.	Remarks D.No.2969/16, Dt.2-2-17. (DTR plinth clearance)	D.No.2414/16, Dt.17-01-2017	Sanctioned vide sanction No.384/2016-17 and D.No.2999/16, Dt.06-02-2017.
3	24-05-2015, 09:30 hrs	Kamareddy	Yellareddy	Lingampet	Day	1 No. Cow	Sri.Bandi Bala Pochaiiah S/o Chinna Parvaiah R/o Lingampally-K(V), Lingampet(S)	SS-12/25 KVA DTR at Banapur feeder	20,000	While Cow wondering near DTR structure, unfortunately came into contact with live equipment and got electrocuted, died on the spot.	Remarks called due to not entered in ATS and communicated to vide D.No.1354, Dt.09-10-15 to DE(O)KMR &	Proposal submitted vide D.No.2180/15, Dt:25.01.16	Sanctioned vide Sanction No.219/2015-16, D.No.706/15, Dt:03-02-2016.
4	29-05-2015, 17:00 hrs	Nizamabad	Nizamabad(R)	Sarangapur	Day	2 Nos. Cows	Sri B. Mangya, S/o. Sakariya, R/o. Malkapur Thanda	SS-18/25 KVA DTR at Muthakunta(V)		While grazing the grass, they touched 11 KV bush rod of SS-18/25 KVA DTR at Muthakunta(V) and got electrocuted, died on the spot.		Proposals submitted and remarks copy communicated to DE(O)NMB vide D.No.1094, Dt.8-9-15	
5	02-06-2015 14:40 hrs	Armoor	Bheemgal	Sirikonda	Day	2 Nps. she Buffallows	1) Sri.Pyalta Chinna Narsaiah S/o Ramulu 2) Sri.Bongu Chinna Gangaram S/o Pochaiiah R/o Chinna Valgote(V), Sirikonda(S)	SS-2/100 KVA, SS-17/3x16 KVA at Chinna Valgote(V)	40000		Detail report called from DE(Op)/ARR vide D.No.1323/15, Dt:03-10-2015 & remarks called for (ATS) D.No.1890/15, Dt:29.12.15	D.No.1351/16, Dt.16-09-2016.	Sanctioned vide sanction No.165/16-17 and D.No.1864/16, Dt.29-10-2016.
6	03-06-2015 07:30 hrs	Kamareddy	Yellareddy	Lingampet	Day	1 No. Cow	Sri.Darawath Humlanayak S/o Tharya Naik R/o Mumbojipet(V), Lingampet(S)	SS-14/25 KVA DTR at Mumbojipet(V)		While Cow eating the grass near DTR structure unfortunately its tail contact with live conductor got electrocuted, died on the spot.		1) Exgratia proposal submitted vide D.No.2181/15, Dt:25.01.16 2) Remarks copy communicated to DE(O)KMR D.No.714/15, Dt:04.02.16	
7	05-06-2015 07:00 hrs	Kamareddy	Domaikonda	Bhiknors(S)	Day	1 No. she buffalo	Sri Errolla Siddalah, S/o. Mallaiah, R/o. Mallupally(V)	SS-19 & 20, 2x15 KVA DTRs Mallupally(V)		The she buffalo touched to the earth wire and got electrocuted died on the spot due to current passing through the GI wire get the return supply to the earth pipe.		1) Proposals submitted vide D.No.2546/15, Dt.02-03-2016. 2) CGM remarks copy communicated (D.No.986/15, Dt.16-3-16)	

Sl. No.	Date and time of accident	Division	Sub-Division	Section	Day/Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Cause of accident	Remarks	Proposal submitted	Sanctioned/Rejected
8	05-06-2015 07:00 hrs	Kamareddy	Domaikonda	Bhiknoor(S)	Day	1 No. she buffalo	Sri Macharla Bala Goud, S/o. Rama Goud, R/o. Bhagirathpally(V)	SS-17/25 KVA DTR at Bhagirathpally(V)		When the bull is went for grass it is came in contact with the HT line bush rod of DTR, the bull is electrocuted and died on the spot. At the time of accident single phase supply is extended as per schedule and 11 KV HG fuse blown off.		1) Proposals submitted vide D.No.2545/15, Dt.02-03-2016. 2) CGM remarks copy communicated (D.No.987/15, Dt.16-3-16)	
9	05-06-2015 9:10 hrs	Armoor	Armoor	Mupkal	Day	1 No. She buffalo	Sri Nela Limbanna, S/o. Bojanna, Bassapur(V)	SS-16/25 KVA at Bassapur		The she buffalo touched the 11 KV B-ph. Of the DTR with mouth, got electrocuted and died on the spot.	Remarks copy communicated to DE(O)Armoor vide D.No.1095/15, Dt.8-9-15.		
10	05-06-2015 10:30 hrs	Armoor	Armoor	Armoor	Day	1 No. She buffalo	Sri.Gaddam Rajareddy S/o Chinna Reddy R/o Ankapur(V)	SS-46/100 KVA, Ankapur(V)	20000	The She buffalo touched to GI Earth pipe got electrocuted and died on the spot.		Exgratia proposal submitted	Sanctioned vide Sanction No.82/2015-16, D.No.1734, Dt:12-08-2015.
11	05-06-2015	Nizamabad	Nandipet	Noothpally	Night	1 No. She buffalo	Rampuram Bhumanna, S/o Poshanna, R/o Shapoor(V), Noothpally(S)	SS-1/100KVA Shapoor	20000	She buffalo rubbed the earth wire with the body and got electrical shock and died on spot		Exgratia proposal submitted D.No.2170/15, Dt:23.01.16	Sanctioned vide Sanction No. 213/2015-16, D.No.693, Dt:02-02-2016.
12	12-06-2015 09:30 hrs	Nizamabad	Bodhan	Yedapally	Day	2 Nos. buffalos	Sri.Tadem Ravi S/o Durgalah, R/o Pocharam(V), Yedapally(S) & (M)	SS-VII, Pocharam(V), Yedapally(M)	40000	The 2Nos. She Buffalows while grazing came into contract with the LT wire of SS-VII, the LT line was cut and fallen on the ground due to gail and wind. The Buffalows touches the LT line and got electrocuted and died on the spot.		Exgratia proposals submitted to CGM vide D.No.899/15-16, dt.19-8-15.	Sanctioned vide Sanction No.128/2015-16, D.No.2915, Dt:23-10-2015.
13	15-06-2015 08:30 hrs	Nizamabad	Nandipet	Nandipet	Day	1 No. She buffalo	Sri Talveda Hanmandloo, S/o. Bhloomanna, R/o. Velmal(V)	SS-61/15 KVA Velmal(V)	20000	Due to gale & wind occurred on 14-06-2015 during night hours, the service wire is cut and one side of service wire touches the pole and remaining side is consumer side fall on the ground, unfortunately the buffalo touches the pole and got electrocuted and died on the spot.		Exgratia proposals submitted vide D.No.1286/15-16, dt:29.09.15	Sanctioned vide Sanction No.160/2015-16, D.No.2915, Dt:19-11-2015.
14	18-06-2015 08:30 hrs	Nizamabad	Nandipet	Makloor	Day	1 No. He buffalo	Sri.B.Raja Mchan R/o Gangaramanja(V)	SS-12, Gangaramanda(V)		When eating grass near neutral wire of SS-12, 15 KVA DTR, then electrocuted and died on the spot.	Reports not received		
15	20-06-2015 18:00 hrs	Nizamabad	Nizamabad Rural	Dichpally	Day	1 No. Bullock	Sri.Pembari Pedda Rajanna S/o Linganna R/o Mallapur(V)	Mallapur(V)		Bullock touched to transformer 11 KV bushes while eating grass in the field, electrocuted and died.	Remarks copy communicated to DE(O)Nzb vide D.No.1096/15, Dt.8-9-15.		
16	21-06-2015 15:40 hrs	Nizamabad	Nandipet	Makloor	Day	2 Nos. Goat	Sri.Armoor Nadpi Gangaram S/o Pedda Gangaram R/o Chinnapur(V)	SS-1, Mainidipally(V)		When goats are eating near the idle LT line fallen on the ground, a live Agl. service wire passing above the idle LT line. The Agl service wire melted and touched the idle LT line, then goats are electrocuted and died on the spot.	Reports not received		

Sl. No.	Time of accident	Division	Sub-Division	Section	Day/Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Cause of accident	Remarks	Proposal submitted	Sanctioned/Rejected
17	23-06-2015 07:30 hrs	Armoor	Armoor	Perkit	Day	1 No. Ox	Sri.Jangam Rajeshwar S/o Gangaram R/o Subriyal(V)	SS-29(100 KVA), Subriyal(V)		Due to failure of 11 KV Pin insulator near SS-29(100 KVA DTR) at Subriyal(V), 11 KV Subriyal Ag-I feeder conductor snapped and fallen on Ox and electrocuted died on the spot.	Reports not received	-	
18	25-06-2015 14:00 hrs	Kamareddy	Domaikonda	Bhiknoor	Day	1 No. buffalo	Nanavath Ramulu, S/o. Thulasiram, Arepally Thanda(V)	SS-05/100 KVA DTR, Arepally Thanda		The Existing live LT conductor wire got snapped and fell down on wet bushes, the buffalo went for eating grass, came in contact with the live LT conductor and electrocuted and died on the spot.		Proposals submitted to CGM vide D.No.823/15, Dt.7-8-15	
19	27-06-2015 20:30 hrs	Nizamabad	Nandipet	Gottimukkala	Night	1 No. She buffalo	Sri P. Chinnaiah, S/o. Chinnaiah, R/o. Kalledi(V)	SS-61/15 KVA Kalledi(V)	20000	Conductor snapped near SS-61/15 KVA DTR and fallen on the she buffalo got electrocuted and died on the spot.		Exgratia proposals submitted vide D.No. 1287/15-16, dt:29.09.15	Sanctioned vide Sanction No.129/2015-16, D.No.2914, Dt:23-10-2015.
20	30-06-2015 18:00 hrs	Nizamabad	Bodhan	Renjal	Day	1 No. She buffalo	Sri.Panula Mogleiah S/o Pedda Yellaiah R/o Kunepally(V)	SS-3(100 KVA), Kunepally(V)		She buffalo touched the transformer HT bush rods while eating the grass in the field, electrocuted and died on the spot.	Reports not received		
21	02-07-2015 07:30 hrs	Kamareddy	Kamareddy(R)	Machareody	Day	1 No. She buffalo	Dhammannapeta Gangamani, W/o. Narsimloo, H.No.2-9, Bhavanipet(V)	H.No.2-9, Bhavanipet	20000	The buffalo has touched to single phase DTR neutral earth wire while passing from near to pole when raining, got electrocuted and died on the spot.		1) Exgratia proposals submitted vide D.No.50/16, dt: 06.04.16 2) Remarks called from CGM(OP) vide D.No.164/16, Dt.27-04-2016 vide Endt.No.396/16, dt.19-05-2016. 3) Exgratia proposals re-sub. Vide D.No.795/16, Dt.12-7-16.	Sanctioned vide Sanction No.84/2016-17, D.No.1132/16, Dt:04-08-2016.
22	18-07-2015, 16:00 Hrs	Nizamabad	Bodhan	Bodhan Rural	Day	1 No. Ox	Yembari Istari S/o Shivaiah R/o Ambam(V), Bodhan(M)	SS-31 (25 KVA) Bardipur	20000	1No. Ox touched the transformer HT bush rods while eating the grass in the field, electrocuted and died on the spot.		Exgratia proposals submitted vide D.No. 1274/15, dt:24.09.2015	Sanctioned vide Sanction No.135/2015-16, D.No.3009, Dt:31-10-2015.
23	21-07-2015, 10:25 Hrs	Nizamabad	Nizamabad Rural	Nizamabad Rural	Day	2 Nos. buffalo	Kattam Bhudevi, Nagaiah R/o Nyalkal(V), Nizamabad Rural(M)	W/o SS-62, location No.KG 6/1, Nyalkal(V)	40000	Accident occurred due to 2 Nos. buffalos passing near electrical pole and they pushed it, while conductor snapped and fallen on the 2 Nos. buffalos and spot died.		Exgratia proposals submitted vide D.No. 1119/15, dt:14.09.2015, Re-Sub vide D.No.1956/15,dt:07.01.16	Sanctioned vide Sanction No.204/2015-16, D.No.598, Dt:22-01-2016.

Sl. No.	Date and time of accident	Division	Sub-Division	Section	Day/Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Cause of accident	Remarks	Proposal submitted	Sanctioned/ Rejected
24	22-07-2015 17:00 hrs	Armoor	Morthad	Morthad	Day	1 No. Ox	Sri Enugu Mallesh, S/o. Rajaram, R/o. Sunket(V)	Near SC colony at Sunket(V)		Low height of DTR plinth (touching HT bushes), Ox went near to DTR to having grass and touched to the 11 KV bush road of DTR, got electrocuted and died on the spot.		1) Exgratia proposal submitted D.No.2593/15, Dt:04.03.16 2) Remarks copy D.No.1012/15, Dt.21-03-16 of CGM(OP) communicated vide D.No.194/16, Dt.20-4-16.	✓
25	26-07-2015	Kamareddy	Domakonda	Bhiknoor(N)	Day	1 No. she buffalo	Sri Kothi Siddaiah, S/o. Rajaiah, R/o. Shivaipally(V), Bhiknoor(M)	SS-24, 25 KVA, Shivaipally		When the she buffalo is went for grass it is came in contact with the HT line bush rod of DTR and died on the spot. At that time supply is extended as per schedule & HG fuse blown off.		1) Remarks copy communicated to DE(O)KMR vide D.No.1669/15, Dt.11-12-15, received on 29-3-15 and proposals submitted vide D.No.47/16, Dt.06-04-2016. 2) Remarks called from CGM(OP) vide D.No.159/16, Dt.27-04-2016 vide Endt.No.395/16, dt.19-05-2016.	✓
26	28-07-2015, 09:30 Hrs	Nizamabad	Nizamabad Rural	Bardipur	Day	1 No. She buffalo	Mothukula Venu Goud S/o Chinna Goud R/o Bardipur	SS-41, 25 KVA, Yanampally, Bardipur(S)		She buffalo touched the transformer HT bush rods while grassing in the field, electrocuted and died on the spot.	Detailed report called Vide D.no.1828/15, Dt23.12.15		✓
27	31-07-2015, 11:55 Hrs	Nizamabad	Nizamabad Town	D-IV/ Nizamabad Town	Day	1 No. She buffalo	Manukonda Hemanth Kumar R/o Madhavnagar	SS-37, 25 KVA, Madhavnagar		buffalo scraching the body to the DTR plinth, the buffalow horns touched the 11 KV Jumper and got electricuted and died on the spot.	Detailed report called Vide D.no.1827/15, Dt23.12.15		✓
28	08-08-2015,	Armoor	Armoor	Perkit	Day	1 No. She buffalo	Golla Vallem Das S/o Bajanna R/o Perkit	SS-103/100 KVA DTR, Perkit(V)		She buffalo touching the Stay wire on SS-103/100 KVA DTR got electrocuted and died on the spot.	Detailed report called Vide D.no.1824/15, Dt23.12.15		✓
29	09-08-2015, 06:30 Hrs	Kamareddy		Lingampet	Day	1 No. She buffalo	Sri Revuri Gundaiah, S/o Lingaiah	SS-28/15KVA DTR SS Reddy	20000	She buffallo eating grass at DTR and got contacted with the earth wire then electrocuted and died on the spot.		Exgratia proposals submitted vide D.No. 1127/15-16, dt:14.09.15 & Re-submitted vide D.No.2183/15, Dt:25.01.16	Sanctioned vide Sanction No.22115-16, D.No.752, Dt:38-02-2016.



Sl. No.	Date and time of accident	Division	Sub-Division	Section	Day/Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Cause of accident	Remarks	Proposal submitted	Sanctioned/Rejected
30	25-08-2015, 15:30 Hrs	Nizamabad	Bodhan	Bodhan Rural	Day	1 No. Cow	Syed Rafeeq S/o Asadullah R/o Ootpally(V), Bodhan(M)	SS-06/63 KVA DTR, Ootpally(V)	20000	The Cow came near LT fuse box of SS-06/63 KVA DTR and touched to fuse box got electrocuted and died on the spot.		1) Detailed report called Vide D.no.1825/15, Dt:23.12.15. 2) Exgratia proposals submitted vide D.No.168/16, Dt.20-04-16.	Sanctioned vide sanction No.23/2016-17 and D.No.408/16, Dt.21-05-2016.
31	30-08-2015, 05:30 hrs	Banswada	Bichkunda	Jukkai	Day	1 No. she buffalo	Sri Vijaya Prakash, S/o. Jayavanth Rao, R/o. Edgi Small(V)	SS-1/63 KVA, Edgi Small(V)		While eating grass bedside SS-1/63 KVA DTR and already touched the GI earth wire connected to the neutral bush rod of the transformer, she buffalo lift the head and GI wire contacted with transformer phase wire and electrocuted, died on the spot.		Proposals submitted and remarks copy communicated vide D.No.587, 10-7-15 to DE(O)BNS.	
32	09-09-2015 16:00 hrs	Kamareddy	Kamareddy(R)	Machareddy	Day	1 No. cow	Sri Velpugonda Rajaiah, S/o. Ramaiah, R/o. Machareddy(V) & (S)	SS-09/2x25 KVA DTR at Machareddy		The cow has touched to 11 KV bush rod while eating grass on SS-9/2x25 KVA DTR, electrocuted died on the spot.		Exgratia proposal submitted D.No.2169/15, Dt:23.01.16 2) Remarks copy communicated to DE(O)KMR ref D.no.2427/15, dt:17.02.16	
33	22-09-2015	Kamareddy	Domakonda	Bhiknoor(S)	Day	1 No. Bullock	Peddolla Shankaralah, S/o. Mallalah, R/o. Bharathpally(V), Bhiknoor(S)	SS-36/25 KVA DTR at Bhagirthpally		The bullock was went for eating grass, it is came in contact with the 11 KV side bush rod, electrocuted and died on the spot.	Remarks copy communicated to DE(O)KMR vide D.No.1672/15, Dt.11-12-15.		
34	25-09-2015	Kamareddy	Domakonda	Domakonda	Day	1 No. buffalo	Sri Erukala Pedda Lingam, S/o. Yellaiah, R/o. Domakonda(V)	SS-63/100 KVA, Domakonda		When the buffalo was went for grass, it is came in contact with the LT line service which is wire cut and touched the GI wire, the buffalo was electrocuted and died on the spot	Exgratia proposal returned to DE/O&C/KMR vide D.No.2179/15, Dt.25-01-16 for relevant documents		
35	04-11-2015, 14:00 hrs	Kamareddy	Yellareddy	Lingampet	Day	1 No. Bullock	Sri Yerra Mallaiah, S/o. Annaiah, R/o. Pothalpally(V)	SS-29/16 KVA DTR	20000	The stay wire was cutout with plough and came in contact with 11 KV bush rod below the guy insulator, the bullock used for plough, got electrocuted and died on the spot.		Exgratia proposal submitted vide D.No.2246/15, Dt:01.02.16	Sanctioned vide Sanction No. 226/2015-16, D.No.864, Dt:10-02-2016.
36	04-11-2015, 13:36 hrs	Banswada	Banswada	Chandoor	Day	1 No. Cow	Sri B. Pothareddy, S/o. Ramreddy, R/o. Mosra(V), Chandoor section	Mosra		Low height of DTR plinth (touching HT bushes) while the cow went for eating the grass touched the LT HG fuse set open wiring, got electrocuted and died on the spot.	Remarks CGM D.No.2886/16, Dt.24-01-17 (DTR height)	D.No.2248/16, Dt.28-12-2016	

Sl. No.	Date and time of accident	Division	Sub-Division	Section	Day/Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Cause of accident	Remarks	Proposal submitted	Sanctioned/Rejected
37	06-11-2015 15:30 hrs	Kamareddy	Yellareddy	Lingampet	Day	1 No. Bullock	Sri Maloth Peerya, S/o. Dhanja, P/o. Parmalla Thanda(V), Lingampet(S)	SS-24/16 KVA at Parmalla Thanda	20000	Low height of DTR plinth (touching HT bushes), bull was eating the grass near SS-24/16 KVA DTR, bull mouth got in contact with 11 KV bush rod got electrocuted and died on the spot.		1) Exgratia proposal submitted D.No.2594/15, Dt:04.03.16 2) Remarks copy D.No.1026/15, Dt.21-03-16 of CGM(OP) communicated vide D.No.193/16, Dt.20-4-16. 3) Proposals re-submitted vide D.No.703/16, Dt.24-06-16.	Sanctioned vide sanction No.61/2016-17 and D.No.906/16, Dt.12-07-2016.
33	12-01-2016, 07:30 hrs	Nizamabad	Nandipet	Makloor	Day	1 No Cow	Smt Suryala Bhoodevi, W/o Sailoo, R/o Madhanpally	SS-25/25KVA DTR, Madhanpally	40000	While grazing the cow near SS-25/25KVA at Madanpally camp the cow accidentally got in touch with 11Kv HT line and got Electrocuted and died on the spot.	1) Proposals submitted vide D.No.566/16, Dt.10-06-16. 2) Remarks called by CGM vide D.No.809/16, Dt.29-06-16.	Proposal re-submitted vide D.No.1302/16, Dt:09-09-16	Sanctioned vide sanction No.158/16-17 and D.No.1852/16, Dt.29-10-2016.
39	26-01-2016, 14:15 hrs	Armoor	Armoor	Mupkal	Day	1No. She buffalo	Sri Palem Rajeshwar, S/o. Rajanna, R/o. Kothapally(V)	SS-44/25 KVA		She buffalo touched to 11KV Bush of SS-48 got electrocuted & died on spot. The DTR plinth is 6 ft height from the ground level.		1) Exgratia proposal submitted vide D.No.49/15, Dt:06.04.16 2) Remarks called from CGM(OP) vide D.No.174/16, Dt.27-04-2016 & Endt.No.394/16, dt.19-05-2016. 3) Re-sub vide D.No.903/16, Dt:26.07.2016	
40	03-02-2016 11:30 hrs	Nizamabad	Nandipet	Noothpally	Day	1 No. She buffalo	Sri Loka Chinnaiah, S/o. Gangaram, R/o. Noothpally(V)	SS-26/100 KVA, Noothpally, SC.No.743/V, Agl. Starter panel board		Buffalo was rubbed to Agl. Pump set bore starter panel board near SC.No.743/V and touched live service wire and got electric shock and dead.	IMP	Exgratia proposal submitted vide D.No.2592/15, Dt:04.03.16	Rejected by CGM(OP) vide D.No.1024/16, Dt.21-03-2016
41	01-03-2016 12:30 hrs	Nizamabad	Bodhan	Bodhan(R)	Day	1 No. Cow	Sri Baride Vittal Reddy, S/o. Narsareddy, R/o. Saloora(V)	Saloora	30000	Due to gale & wind occurred on 29-02-2016, the LT line snapped and fallen on the road, while crossing Cow came in contact with live snapped wire, got electrocuted and died on the spot		D.No.2636/16, Dt.09-02-2017.	Sanction No.411/16 & D.No.3203/16, Dt.09-03-2017.
42	04-03-2016 10:05 hrs	Nizamabad	Bodhan	Bodhan(T-2)	Day	2 Nos. she buffalos	Sri Veeragandham Haribabu, S/o. Sambaiah, R/o. Saloora Camp(V)	SS-2/100 KVA DTR, Saloora Camp		While grazing the grass came near express feeder on SS-2/100 KVA DTR and rubbed, which one of the phase pin binding is broken and conductor hanged in the middle of air, when 2 Nos. she buffalows came in to contact with hanged conductor, got electrocuted and died on the spot.	1) Returned D.No.2494/16, Dt.25-01-2017. (2 buffalos died but in certificate mentioned 1 No.)	D.No.3070/16, Dt.21-03-2017.	Sanction No.03/17 & D.No.90/17, Dt.13-04-2017.

Sl. No.	Date and time of accident	Division	Sub-Division	Section	Day/Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Cause of accident	Remarks	Proposal submitted	Sanctioned/Rejected
43	18-03-2016 19:30 hrs	Kamareddy	Kamareddy(R)	Machareddy	Night	1 No. buffalo	Sri Velma Rangolla Narsareddy, S/o. Nadipi Ramaian, R/o. Arepally(V)	SC.No.277, H.No.1- 83, Arepally(V)	20000	The LT line wires are given to starter box are fallen down on earth. While the buffalo was grazing the grass in field, bite the LT cable wire, electrocuted died on the spot.		1) Remarks called for vide D.No.296/16, Dt:07.05.16 2) Proposals submitted to CGM(Op) vide D.No.788/16, Dt.11-07-2016.	Sanctioned vide sanction No.96/2016-17 and D.No.1308/16, Dt.27-08-2016.

15-16 43 - 22 Pindingu - 1. Rejected - 2nd try (10) = 20 Pay 45%.

**NORTHERN POWER DISTRIBUTION COMPANY OF TELANGANA LIMITED**  
**OPERATION CIRCLE, NIZAMABAD**  
**Animals electrical accidents occurred during the financial year 2016-17**

Sl. No.	Date and time of accident	Division	Sub-Division	Section	Day/Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Cause of accident	ATS No.	Remarks	Proposal submitted	Sanctioned/ Rejected
1	09-04-2016 8:30 hrs	Kamareddy	Kamareddy(R)	Machareddy	Day	1 No Buffalo	Smt. Rendla Rajavva, W/o. Narayana, Laxmiravulapally(V)	SS-18m 19&20/3x15 KVA DTR, Laxmiravulapally(V)	40000	Earthing problem, while the buffalo was grazing the grass near by SS-18,19&20/3x15 KVA Dtrs the buffalo leg was touched to the failed earth pit and electrocuted and died.		Remarks called from DE vide D.No.297/16, Dt.07-05-2016.	Proposals submitted to CGM(Op) vide D.No.786/16, Dt.11-07-2016.	Sanctioned No.81/2016-17 and D.No.1094/16, Dt.29-07-2016.
2	17-04-2016 11:58	Nizamabad	Nandipet	Navipet	Day	1 No She Buffalo	Sri Kondapuram Chinna Poshetty, S/o Durganna, R/o Naleshwar	SS-56/25 KVA Naleshwar	40000	While grazing grass moved to DP side and electrocuted and died on the spot		1) Proposals submitted vide D.No.659/16, Dt.22-06-16. 2) ATS called by CGM vide D.No.863/16, Dt.5-7-16.	Proposal re-submitted vide D.No.1301/16, Dt.08-09-16	Sanctioned No.166/2016-17 and D.No.1863/16, Dt.29-10-2016.
3	30-04-2016 17:00	Nizamabad	Nizamabad Rural	Dichpally	Day	1 No. She Buffalo	Sri Lakshmi Kista Reddy, S/o Gangaram, R/o Suddulam	Suddulam(V)	40000	Due to heavy gale and wind 2 Nos. LT poles damaged and LT lines fallen on the ground. when she buffalo contact with LT lines, got electrocuted and died on the spot.		The ADE not entered DR in ATS, hence returned vide D.No. 716, Dt. -7-16.	D.No.2780/16, Dt.23-02-2017	Sanction No.422/16 & D.No.3330/16, Dt.22-03-2017.
4	30-4-2016 23:10 hrs	Nizamabad	Nizamabad Rural	Nizamabad Rural	Night	40 Nos. Mob of goats	Sri Badavath Gangaram, S/o. Gangya, R/o. Yanampally(V)	Yanampally (V)		Short circuit occurred on LT AB cable which is passing over hut consisting of 40 Nos. Mob of goats. Sparks fallen on the above hut and burnt Mob of goats died on the spot.		Remarks called by CGM vide D.No.2281/16, Dt.8-12-16.	1) D.No.1918/16, Dt. 21-11-16. 2) Re-sub.D.No.87/17, Dt.18-04-2017.	
5	02-05-2016 16:00	Nizamabad	Bodhan	Bodhan Rural	Day	4 Nos. Cows	Sri.Banavath Rathiram S/o Sangeeti R/o Kalpole Thanda	Near SS-2/100 KVA Ootpally(V)	160000	Due to heavy gale and wind tree branches are fell down on the LT line of SS-01 of Seri Bibipet, while removing the tree branches along with ALM Sri.Raja Narsu. Back feeding supply is entered from the Medak District supply which are using double supply by the consumer, the supply is entered through electrical wire and he is electrocuted he is shifted to hospital but on the way he is expired.	001152	1) Only Form-A (ATS No.001152) received. 2) Reports called from DE(O) vide D.No.1123/16, Dt.12-08-16.	D.No.2509/16, Dt.27-01-2017	Sanctioned No.397/16-17 and D.No.3064/16, Dt.16-12-2016.
6	02-05-2016 08:30	Nizamabad	Bodhan	Renjal	Day	1 No She Buffalo	Sri.Gujjala Gangareddy S/o Hanmandi R/o Tadbiloli(V)	SS-8/100 KVA Tadbiloli(V)		She buffelow rubbed nearer to LT pole at SS-8/100KVA Tadbiloli, the LT pole has broken and line LT line fallen on Buffelow got electrocuted and died on the spot.		1) Only Form-A (ATS No.001151) received. 2) Reports called from DE(O) vide D.No.1123/16, Dt.12-08-16.		
7	05-05-2016 07:00 hrs	Kamareddy	Kamareddy(T)	Kamareddy(R)	Day	1 No She Buffalo	Sri Thota Lingam, S/o. Balaiah, R/o. Kyasampally(V)	SS-02/100 KVA DTR at Kyasampally	40000	Due to gale & wind occurred on 05-05-2016, LT electrical lines fallen on ground at SS-02/100 KVA DTR, when she buffalo passing in that area got contacted with the fallen electrical live wires electrocuted and died on the spot.	001632		D.No.1929/16, Dt.21-11-2016	Sanctioned No.292/16-17 and D.No.2566/16, Dt.20-12-2016.

Sl. No.	Date and time of accident	Division	Sub-Division	Section	Day/Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Cause of accident	ATS No.	Remarks	Proposal submitted	Sanctioned/ Rejected
8	06-05-2016 10:30	Kamareddy	Kamareddy(R)	Machareddy	Day	1 No She Buffalo	Boosi Mallalah, S/o. Narsainh, H.No.1-63, Manthini, R/o. Devunipally(V)	1-63, Manthini, Devunipally	40000	The buffalo was gone to grassing the grass in field near SC.No.270, heavy gale & wind was occurred on 06.05.16 on Machareddy(S) due to that insulator was blown and 11KV wire was snapped and fallen on earth. That snapped wire was touched to the buffalo and electrocuted and died.		Reports called from DE vide D.No. /16, Dt. -06-16.	Proposals submitted to CGM(Cp) vide D.No.787/16, Dt.11-07-2016.	Sanctioned No.85/2016-17 and D.No.1133/16, Dt.04-08-2016.
9	07-05-2016	Armoor	Armoor	Jakranpally	Day	1 No Cow	Sri Kandula Sagar, S/o Pedda Sayanna, R/o Keshipally(v), Jakranpally(S)	SS-57/25KVA DTR at Keshipally(v)		the she buffalo mouth touched to DTR jumper on 11KV side of SS-57, 25KVA DTR at Keshipally(v) got electrocuted and died on spot		Remarks called to DE vide D.No.560/16, Dt.10-06-2016.		
10	08-05-2016 08:30	Nizamabad	Bodhan	Yedpally	Day	1 No. Cow	Shaik Ghouse S/o Yusuf R/o Yedpally	SS-62/25 KVA DTR at Yedapally	40000	While grazing cattle group one of the Cow came near to LT line which was fallen on ground due to broken poles (gale and wind occurred on 07-05-2016) and came in contact get electricuted and died.		1) Only Form-A (ATS No.001153) received 2) Reports called from DE(O) vide D.No.1123/16, Dt.12-08-16.	D.No.2487/16, Dt.25-01-2017	Sanctioned No.396/2016-17 and D.No.3063/16, Dt.16-02-2017.
11	08-05-2016 09:30	Kamareddy	Kamareddy(R)	S.S.Nagar	Day	2 Nos. Goats & 1 No. Ram Lamb	Sri Yedla Lingam, S/o. Balaiah, R/o. Adloor Yellareddy(V)	Adloor Yellareddy		11 KV wire was snapped and fallen on ground near Sri Paidi Janardhan Bore well due to heavy gale & wind occurred on 07-05-2016, 2 Nos. Goats & 1 No. Ram lamb while grazing the grass near snapped wire, got electrocuted and died on the spot.	001782	Remarks by CGM(OP) D.No.3024/16, Dt.10-02-17.	D.No.2466/16, Dt.21-01-2017	
12	10-05-2016 16:00	Nizamabad	Nizamabad Rural	Nizamabad Rural	Day	1 No. She Buffalo	Amgoth Vittal S/o Sakram R/o Chandu Nayak Thanda, Amrabad(V)	SS-06/1, 63 KVA, Amrabad(V)		Due to heavy gale & wind 1 No. span come near to ground level on SS-06/1, 63 KVA DTR of Amrabad(V), the she buffalo passed below the LT line, touched the line got electrocuted and died on the spot		ATS called by CGM vide D.No.808/16, Dt.29-06-16.	1) Proposals submitted vide D.No.576/16, Dt.14-06-2016. 2) Re-sub D.No.115/17, dt.24-04-17.	
13	12-05-2016 20:32 hrs	Nizamabad	Bodhan	Bodhan (T-2)		1 No. Ox	K. Sailu, S/o. Sayanna, Hunsa(V)	SS-15/100 KVA, SC.No.554 at Hunsa(V)	40000	Due to no crop the farmer has taken the panel box which is fixed to wooden board to home and leaving the live incoming service wire on the ground, while grazing the Ox came in contact with live service, got electrocuted and died on the spot.	001154	1) Only Form-A (ATS No.001154) received 2) Reports called from DE(O) vide D.No.1123/16, Dt.12-08-16.	D.No.2490/16, Dt.25-01-2017	Sanctioned No.399/16-17 and D.No.3066/16, Dt.16-02-2017.
14	22-05-2016 08:15	Nizamabad	Nizamabad Rural	Bardipur	Day	1 No. She Buffalo	Sri Ullengula Yadagiri, S/o. Ramulu, R/o. Devapally, Suddapally(V)	SS-8/16 KVA, Suddapally(V)	40000	While she buffalo grazing the tree branches near SS-8/16 KVA DTR, top tree branch touched to 11 KV line and passed electricity through tree, got electricuted and died.	001710	1) Reports not received 2) Reports received on 4-1-17	D.No.2450/16, Dt.19-01-2017	Sanctioned No.382/16-17 and D.No.2994/16, Dt.06-02-2016.

Sl. No.	Date and time of accident	Division	Sub-Division	Section	Day/Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Cause of accident	ATS No.	Remarks	Proposal submitted	Sanctioned/Rejected
15	05-06-2016 07:30 hrs	Banswada	Banswada	Birkur	Day	1 No. She Buffalo	Sri Shivarathri Poshaiyah, S/o. Somalah, R/o. Kamshetpally(V), Birkur section	SS-1/25 KVA, Namli		While she buffalo rubbing the LT say wire on LT 3-ph. 3 W/L of SS-1/25 KVA DTR of Namli(V), the supply passed through stay wire, got electrocuted and died on the spot.	001694	1) Proposals received on 1-12-16 vide D.No.542/16, Dt.28-11-16. 2) Remarks called vide D.No.2291/16, Dt.02-01-2017.	D.No./16, Dt.-01-2017	
16	08-06-2016 06:30	Banswada	Bichkunda	Pitlam	Day	1 No. She Buffelaw	Sri Iraj Sailoo S/o. Laxmaiah, R/o. Chinnakodappal(V)	1-05, Ch.Kodappal	40000	She buffalo eating the grass near DTR DP, the street phase cut and touched cross arm of neutral and touched the same, got electrocuted and died on the spot.	001650	Returned vide D.No.1481/16, Dt.03-10-2016. (Reports date not matching)	D.No.1992/16, Dt.26-11-2016	Sanctioned No.277/16-17 and D.No.2347/16, Dt.19-12-2016.
17	08-06-2016 18:00	Banswada	Bichkunda	Pitlam	Night	1 No Cow	Gyara Nagireddy, S/o Balreddy, R/o Chinna kodappal	SS-9/15KVA DTR		While crossing cow near DTR DP the street light phase insulator damaged and conductor touched to neutral and cow came in contact with earth pipe got electrocuted and died		Reports not received		
18	08-06-2016 07:00 hrs	Banswada	Banswada	Birkur	Day	2 Nos. she buffalos	Sri Abdul kaleem, S/o. Kareem, R/o. Baswaipally(V)	At Baswaipally field	80000	The 11 KV someshwar Indl. Feeder snapped and fallen on 3-ph. 3 W/L line of SS-1/100 KVA DTR. While 2 Nos. buffalos came in contact with the snapped conductor, got electrocuted and died on the spot.		DR, Sketch, ATS not received and remarks called vide D.No.1066/16, Dt.08-08-16.	D.No.1445/16, Dt.28-0-2016	Sanctioned No.194/2016-17 and D.No.1936/16, Dt.03-11-2016.
19	08-06-2016 13:30	Kamareddy	Kamareddy(R)	S.S.Nagar	Day	1 No. she buffalo	Sri Kala Ravinder, S/o. Kala Balaiah, R/o. Uppalwai(V)	SS-24/15 KVA DTR, Uppalwai(V)	40000	While buffalo grazing the grass near 15 KVA DTR, touched the DTR earth wire, got electrocuted and died on the spot.		Reports received on 17-8-16	D.No.1219/16, Dt.30-8-16.	Sanctioned No.151/2016-17 and D.No.1851/16, Dt.29-10-2016.
20	08-06-2016 18:00	Nizamabad	Nizamabad (T)	D-V/NZB		2 Nos. she buffalos and 1 No Child Buffalo	T. Raja reddy, S/o Sayanna, R/o Gupanpally(V)	D-V/NZB(T) Gupanpally	120000	Buffalow dashed forcibly to the pole, the conductor got snapped and buffaloes got electrocuted and died on the spot.			D.No.1303/16, Dt.8-9-16.	Sanctioned No.162/2016-17 and D.No.1846/16, Dt.29-10-2016.
21	08-06-2016 11:00 hrs	Nizamabad	Nandipet	Gottimukkala	Day	1 No. she buffalo	Sri Bandi Chinnolla Rajanna, S/o. Peddanna, R/o. Gunjilli(V) in Gottimukkala section	Gunjilli(V)	40000	She buffalo touched to earthing of S-ph. DTR electrocuted and died on the spot.		Reports received on 07-10-16	D.No.1627/16, Dt.21-10-16.	Sanctioned No.203/16-17 and D.No.2046/16, Dt.16-11-2016.
22	08-06-2016 18:30 hrs	Banswada	Bichkunda	Pitlam	Day	1 No. cow	Sri J. Venkat Reddy, S/o. Galreddy, R/o. Chinna Kodappal(V)	2-27, Ch. Kodappal	40000	The Cow while eating the grass near DTR DP the street light phase cut and touched cross arm of neutral, cow contact with earthing of DTR got electrocuted and died.	001528		D.No.1991/16, Dt.26-11-2016	Sanctioned No.279/16-17 and D.No.2345/16, Dt.19-12-2016.
23	08-06-2016 13:00 hrs	Kamareddy	Kamareddy(T)	Tadwai	Day	1 No. Bullock	Sri Sanda Raju, S/o. Chinna Narsaiah, R/o. Demikalan(V)	SS-10/63 KVA DTR, Demikalan		The bullock went to eat the grass near, at that time neutral earthing failed and bullock touched the DTR earth pipe, got electrocuted and died on the spot.	001974	D.No./16, Dt.-03-17 (Earthing failed)		

Sl. No.	Date and time of accident	Division	Sub-Division	Section	Day/Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Cause of accident	ATS No.	Remarks	Proposal submitted	Sanctioned/ Rejected
24	12-06-2016 07:40	Nizamabad	Nandipet	Noothpally	Day	3 Nos. she buffalo	1) Sri Arigela Naganna, S/o. Muthenna 2) Sri Kothur Gangaram, S/o. Mallanna & 3) Gajari Nadipi Rmulu, S/o. Ramanna, R/o. Kudvanpur(V)	SS-35/25 KVA DTR at Thondapur	120000	Due to heavy gale & wind LT line snapped and fallen on Agl. land of Badguna Lasumbai, W/o. Kondur Gangaram, R/o. Shapur near SS-36/25 KVA DTR at Thondakur(V), while grazing 3 Nos. she buffalos got contact with live LT snapped conductor got electrocuted and died on the spot.			Proposals submitted vide D.No.996/16, Dt.28-07-2016.	Sanctioned No.104/2016-17 and D.No.1351/16, Dt.31-08-2016.
25	12-06-2016 16:30 hrs	Armoor	Armoor	Jakranpally	Day	1 No. she buffalo	Smt. Boini Nagamani, W/o. Sudharshan, R/o. Narayanpet(V)	Narayanpet	40000	While she buffalo grazing the grass near LT line of SS-16/100 KVA DTR, accidentally touched to the stay wire, got electrocuted and died on the spot. On observation it is found that, the supporting stay wire is not guy insulator. SC.No.331, Cat-V service wire insulation is failed and touched to stay wire.			D.No.2059/16, Dt.05-12-2016	Sanctioned No.325/16-17 and D.No.2651/16, Dt.28-12-2016.
26	14-06-2016 08:30 hrs	Kamareddy	Kamareddy(R)	S.S.Nagar	Day	3 Nos. she buffalo	1) Sri C. Bhoomaiiah, 2) Sri G. Bairreddy & 3) Sri N. Parvalah R/o. Padrnajwadi(V)	11 KV Kalvaral feeder	120000	due to heavy gale & wind occurred two days before the incident, the 11 KV Kalvaral feeder one phase was snapped and fallen in water pond. The 3 Nos. she buffalos are went to drink the water into the water pond got electrocuted and died on the spot.			D.No.1212/16, Dt.29-08-2016.	Sanctioned No.168/2016-17 and D.No.1862/16, Dt.29-10-2016.
27	16-06-2016 07:00 hrs	Banswada	Banswada	Birkur	Day	2 Nos. she buffalos	Smt. Pandiri Lachavva, W/o. Ramulu, R/o. Bommandevpally (V)	Bommandevpally	80000	The LT 3-ph. 3 W/L of SS-02/100 KVA DTR of Bommandevpally (V) was snapped due to heavy gale & wind and fallen on ground. While 2 Nos. she buffalos eating the grass, came in contact with snapped conductor, got electrocuted and died on the spot.	001693		D.No.2258/16, Dt.24-12-2016.	Sanctioned No.337/2016-17 and D.No.2821/16, Dt.18-01-2017.
28	18-06-2016 17:00	Armoor	Morthad	Morthad	Day	1 No She Buffalo	Bunagiri Jagatheesh, S/o. Gangaram, R/o Morthad	SS-136, Morthad		On SS-136/100 KVA DTR at Morthad LT line at Takkuri Wada Sangam service wire insulation failed and touched nearby fencing, while grazing the buffalo touched to fencing wire got electrocuted and died on the spot.		Reports received on 19-8-16	D.No.1224/16, Dt.31-8-16.	
29	19-06-2016 14:00	Kamareddy	Kamareddy(R)	Machareddy	Day	1 No Ox	?	field		The accident occurred due to Ox touched to support wire, while touching support wire forcibly touched the conductor of line and got electrocuted and died.		Reports not received		
30	19-06-2016 09:30	Nizamabad	Nandipet	Noothpally	Day	1 No She Buffalo	Kanooru Kamhari Rajeshwar, S/o. Rajanna, R/o Noothpally(V)	SS-29, 100 KVA Noothpally(V)	40000	She buffalo touched to earth wire while fighting with other she buffalo near SS-29 Noothpally got electrocuted and died on the spot.			D.No.1315/16, Dt.09-09-2016	Sanctioned No.160/16-17 and D.No.1854/16, Dt.29-10-2016.

Sl. No.	Date and time of accident	Division	Sub-Division	Section	Day/Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Cause of accident	ATS No.	Remarks	Proposal submitted	Sanctioned/ Rejected
31	19-06-2016 15:30	Nizamabad	Nandipet	Makloor	Day	1 No She Buffalo	Sri Uradi Pedda Mallaiah, S/o. Bhoomanna, R/o. Muthyampally(V)	Muthyampally(V)	30000	Due to heavy gale & wind, the LT line pole is damaged and LT XLPE cable snapped fallen on Agl. land and she buffalo went to near damaged LT line while grazing the grass and touching the LT line snapped XLPE cable and died on the spot.		1) Remarks called from CGM vide D.No.1525/16, Dt.19-9-16 informed to DE vide D.No.1519/16, Dt.6-10-16.	1) D.No.1135/16, Dt.12-8-16. 2) Re-sub. Proposals D.No.2706/16, Dt.13-12-16.	Sanction No.410/16 & D.No.3204/16, Dt.09-03-2017.
32	19-06-2016 10:00	Nizamabad	Nizamabad Rural	Dichpally	Day	1 No She Buffalo	Sri Paithya Srinivas, S/o. Kishan, R/o. Triambakpet(V)	SS-17/15 KVA DTR at Triambakpet(V)	40000	while she buffalo grazing near SS-17/15 KVA DTR at Triambakpet(V) touched the earthing wire, due to rain electricity passed through earthing wire and died on the spot.			D.No.1291/16, Dt.6-9-16.	Sanctioned No.164/2016-17 and D.No.1848/16, Dt.29-10-2016.
33	20-06-2016 17:30 hrs	Nizamabad	Nizamabad Rural	Dichpally	Day	1 No She Buffalo	Sri Jarupula Mangya, S/o. Chenna, R/o. Thirmanpally(V)	SS-102/25 KVA DTR at Thirmanpally(V)	40000	She buffalo grazing near SS-102/25 KVA DTR at Thirmanpally(V), the LT line of the DTR fallen on the ground due to rain and the buffalo touched it electrocuted and died on the spot.			D.No.1230/16, Dt.6-9-16.	Sanctioned No.156/2016-17 and D.No.1850/16, Dt.29-10-2016.
34	21-06-2016 12:00	Nizamabad	Nizamabad Rural	Dichpally	Day	1 No She Buffalo	Jerupule Nendye, S/o Chinya, Gangaram Thanda, R/o Thirmanpally	SS-48,25KVA Thirmanpally		The four core cable burst at Toll plaza gate the buffalo touched and died		Reports not received		
35	21-06-2016 13:30 hrs	Banswada	Banswada	Birkur	Day	1 No She Buffalo	Sri Koli Hanmandlu, S/o. Kashiram, R/o. Pedda Damarancha(V), Birkur section	At field of Pedda Damarancha		She buffalo while rubbing LT stay wire on LT 3-ph. 3 W/L of SS-1/100 KVA DTR, supply passed through stay wire, got electrocuted and died on the spot.	001692	Remarks called vide D.No.2292/16, Dt.02-01-2017.	D.No./16, Dt.-01-2017	
36	22-06-2016 16:20	Nizamabad	Bodhan	Bodhan Rural	Day	1 No She Buffalo	Sabavath Jamuna bai, W/o Tarya (Late), R/o Bellal	SS-1/100, Bellal	40000	While grazing she buffalo gone nearer to SS-1/100 KVA DTR stay of LT line and it has rubbed the stay wire, in the course the guy insulator fixed in the middle of the stay has broken at the same time the insulation of service wire on the pole got damaged and passed the supply to the stay and got electrocuted and died on the spot.	001157	1) Only Form-A (ATS No.001157) received 2) Reports called from DE(O) vide D.No.1123/16, Dt.12-08-16.	D.No.1952/16, Dt.23-11-2016	Sanctioned No.291/2016-17 & D.No.2569/16, Dt.21-12-2016.
37	22-06-2016 05:30	Nizamabad	Nizamabad Rural	Dichpally	Day	1 No She Buffalo	P.Srinu, S/o Kishan, H.No. 3-41, Sangyanaik Thanda, Indalwai(v)	SS-17,15KVA, Indalwai		The buffalo touched the support wire and got electrocuted and died		Reports not received		
38	25-06-2016 12:30 hrs	Armoor	Armoor	Perkit	Day	1 No She Buffalo	Sri Aggu Mahipal, S/o. Sayanna, R/o. Mamidipally(V)	SS-12, 100 KVA DTR at Mamidipally	40000	while she buffalo touched the stay wire of LT line of SS-12, 100 KVA DTR at Mamidipally and got electrocuted and died on the spot. On observation at spot, it is found that the support stay wire is not having LT guy insulator and touched the phase wire.			D.No.1292/16, Dt.06-09-2016	Sanctioned No.167/2016-17 and D.No.1849/16, Dt.29-10-2016.
39	26-06-2016 15:00	Nizamabad	Nandipet	Navipet	Day	1 No She Buffalo	Peerval, S/o Kondya, R/o Sriram Thanda, Pothangal, Navipet(S)	SS-28, 25KVA Pothangal, Navipet(S)				Reports not received		



Sl. No.	Date and time of accident	Division	Sub-Division	Section	Day/ Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Cause of accident	ATS No.	Remarks	Proposal submitted	Sanctioned/ Rejected
40	25-06-2016 7:00	Kamareddy	Kamareddy(T)	Lingampet	Day	3 Nos. goats & 1 No. sheep	Sri Eerla Shankaraiah, S/o. Chinna Ashaiah, R/o. Parmalla(V)	Parmalla	28000	Due to heavy gale & wind, the LT conductor fallen on the ground near SS-01/100 KVA DTR, while 3 Nos. goats & 1 No. sheep eating the grass came in to contact with fallen live conductor, got electrocuted and died on the spot.			D.No.1209/16, Dt.29-08-16.	Sanctioned No.159/2016-17 and D.No.1853/16, Dt.29-10-2016.
	27-06-2016 15:00 hrs	Nizamabad	Nandipet	Navipet	Day	1 No. she buffalo	Sri Badavath Paerval, S/o. Kondya, R/o. Sriram Thanda, Pothangal(V)	SS-28/25 KVA DTR, Sriramthanda, Pothangal(V)		While she buffalo eating the grass, touched to 11 KV side HT bush rod near SS-28/25 KVA DTR, got electrocuted and died on the spot.	002012	Remarks (DTR height) D.No.27/17, Dt.10-04-2017.		
41	29-06-2016 16:30	Kamareddy	Kamareddy(R)	Machareddy	Day	1 No. she buffalo	Sri Maggam Ganga Rajavva, D/o. Rajaiah, R/o. Reddypet(V)	SS-32, 33, 34, 35/4x25 KVA DTRs, Reddypet(V)		She buffalo was grazing in the field near SS-32, 33, 34,35/4x25 KVA DTRs the horns are touched to the transformers 11 KV side, electrocuted and died on the spot.		Reports received and remarks called vide D.No.1210/16, Dt.29-8-16 (DTR height).	D.No./17, Dt.-04-2017.	
42	08-07-2016 07:00 to 08:00 hrs	Kamareddy	Yellareddy	Yellareddy	Day	1 No. she buffalo	Sri Talari Anjiah, S/o. Saico, R/o. Lingareddypet(V)	SS-20/15 KVA DTR	40000	The she buffalo went to eat the grass beside SS-20/15 KVA DTR, at that time neutral earthing failed and she buffalo touched the GI earth pipe, got electrocuted and died on the spot.	001878		D.No.2635/16, Dt.09-02-2017	Sanction No.407/16 & D.No.3184/16, Dt.06-03-2017.
43	11-07-2016 12:00 hrs	Nizamabad	Nizamabad(T)	D-V/NZB	Day	1 No. she buffalo	Sri Sambal Reddy, S/o. Venkateshwar, R/o. Mubarak Nagar(V)	Mubarak Nagar(V)	40000	Due to heavy gale & wind, the LT pole fallen on she buffalo, got electrocuted and died on the spot.			D.No.1317/16, Dt.09-09-2016	Sanctioned No.163/16-17 and D.No.1847/16, Dt.29-10-2016.
44	12-07-2016 15:00 hrs	Nizamabad	Nandipet	Noothpally	Day	1 No Bull	Sri Baddam Pedda Sayareddy, S/o. Syareddy, R/o. Noothpally(V) & section	SS-20, 100KVA Noothpally	40000	While eating the grass slipped and fallen on consumer side starter box near SS-20/100 KVA DTR at Noothpally, got electrocuted and died on the spot.			D.No.1316/16, Dt.09-09-2016	Sanctioned No.161/16-17 and D.No.1845/16, Dt.29-10-2016.
45	12-07-2016 11:00 hrs	Armoor	Mcrthad	Yergatla	Day	1 No. she buffalo	Sri Bhathula Rajanna, S/o. Gangaram, R/o. Dharmora(V)	Dharmora		The she buffalo going on the road with wooden tie on the neck, touched the legs while running at the same time the water following near SS30/15 KVA DTR, fallen on the earth pipe and the she buffalo tail touched the DTR	001674	Remarks D.No.2731/16, Dt.18-01-2017 (DTR height)		
46	14-07-2016 20:00 hrs	Banswada	Bichkunda	Nizamsagar	Night	1 No. Ox	Sri Bhachigari Venkatesham, S/o. Bhuchalali, R/o. Singitham(V)	2-4, Singitham	35000	The OX while passing near the DTR structure it touched the live conductor got electrocuted and died.		1) Remarks called by CGM vide D.No.2963/1, Dt.27-12-2016 2) Attended D.No.2467/16, Dt.21-01-2017.	D.No.1990/16, Dt.26-11-2016	Sanctioned No.297/16-17 and D.No.2626/16, Dt.27-12-2016.
47	15-07-2016 19:15 hrs	Kamareddy	Kamareddy(T)	Kamareddy(R)	Night	1 No She Buffalo	Sri Gangavath Bikya @ Lambadi Bikya, S/o. Megya, R/o. Shabdipoor(V)	SS-21/15 KVA DTR at Shabdipur	40000	LT line conductor of SS-21/15 KVA DTR, Shabdipur right Thanda was snapped and fallen on the she buffalo when passing in that area, got electrocuted and died on the spot.	001652	Reports received on 3-11-16	D.No.1928/16, Dt.21-11-2016	Sanctioned No.290/16-17 and D.No.2576/16, Dt.21-12-2016.

Sl. No.	Date and time of accident	Division	Sub-Division	Section	Day/Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Case of accident	ATS No.	Remarks	Proposal submitted	Sanctioned/ Rejected
48	19-07-2016 06:30 to 07:00 hrs	Kamareddy	Yellareddy	Yellareddy	Day	1 No. bullock	Sri Ane Kistalah, S/o. Parvaiah, R/o. Rathnapur(V)	SS-05/25 KVA	40000	The Bullock went to eat the grass beside SS-05/25 KVA DTR and touched 11 KV side busing of the DTR, got electrocuted and died on the spot	001845	1) Detailed reports called vide D.No.1120/16, Dt.12-8-16.	D.No.2634/16, Dt.09-02-2017	Sanction No.408/16 & D.No.3206/16, Dt.09-03-2017.
49	21-07-2016 11:30	Nizamabad	Bodhan	Bodhan Rural	Day	1 No She Buffalo	Sri Mirza Javeed Baig, S/o. Mirza Habeeb Baig, R/o Kopparga(V)	SS-08/15 KVA Kopp1rga	40000	While she buffalo rubbed the stay of LT line of SS-8/15 KVA DTR, in course the guy insulator fixed in the middle of stay has broken and at the same time the insulation of service is damaged and passed supply to the stay, got electrocuted and died on the spot	001720	Reports not received	D.No.2637/16, Dt.09-02-2017	Sanction No.406/16 & D.No.3183/16, Dt.06-03-2017.
50	22-07-2016 9:20 hrs	Nizamabad	Nizamabad(R)	Sarangapur	Day	1 No She Buffalo	Sri Devkotte Jagannath, S/o. Venkat Rao, R/o. Khanapur(V)	Near SS-14/100 KVA DTR, Khanapur	40000	She buffalo grazing the grass near SS-14/100 KVA DTR, at the same time 11 KV Khanapur industrial feeder conductor snapped, fallen on the buffalo and died on the spot.		Reports received on 9-11-16	D.No.1860/16, Dt.16-11-2016	Sanctioned No.265/16-17 and D.No.2260/16, Dt.06-11-2016.
51	22-07-2016 05:30 hrs	Nizamabad	Nandipet	Nandipet	Day	1 No. Bull	Sri Buddanna Narayana Reddy, S/o. Ramulu, R/o. Talveda(V)	SS-202/25 KVA	40000	Bull while eating the grass touched to 25 KVA DTR, got electrocuted and died on the spot.	001846		D.No.2554/16, Dt.31-01-2017	Sanction No.402/16 & D.No.3100/16, Dt.21-02-2017.
52	25-07-2016 15:00 hrs	Armoor	Morthad	Morthad	Day	1 No She Buffalo	Sri Neradi Rajanna, S/o. Linganna, R/o. Gandlapet(V)	Gandlapet(V)	40000	The 11 KV Gandlapet conductor was snapped and fallen in water pond. The she buffalo went to drink the water, got electrocuted and died on the spot.	001346	1) Remarks ciled vide D.No.2057/16, Dt.03-12-16. (Diff.in date & time) 2) Remarka by CGM D.No.2754/16, Dt.9-1-17.	D.No.2253/16, Dt.24-12-2016	Sanctioned No.336/16 & D.No.2822/16, Dt.18-01-2017.
53	26-07-2016 13:15 hrs	Kamareddy	Yellareddy	Lingampet	Day	2 Nos. she buffalos	1) Sri S. Shiva Ramulu, S/o. Ramalah 2) Sri K. Shivalah, S/o. Rajalah, R/o. Lingampet(V) & section	SS-18/100 KVA DTR Town feeder	80000	While eating the grass near SS-18/100 KVA DTR, 2 Nos. 11 KV pin Insulators failed and current passed through the cross arm and pole, touched 2 Nos. she buffalos to pole, got electrocuted and died on the spot.			D.No.1510/16, Dt. 06-10-16.	Sanctioned No.204/16-17 and D.No.2047/16, Dt.16-11-2016.
54	26-07-2016 21:00 hrs	Banswada	Banswada	Birkur	Night	1 No. Ox	Sri Bonthala Sailu, S/o. Saidalah, R/o. Chincholl(V), Birkur section	SS-04/15 KVA, Chincholl(V)		The Ox while rubbing the LT stay wire, the supply passed through stay wire, got electrocuted and died on the spot.	001695	Remarks called vide D.No.2250/16, Dt.02-01-2017.	D.No./16, Dt.-01-2017	
55	27-07-2016 19:30 hrs	Kamareddy	Yellareddy	Nagireddypet	Night	1 No She Buffalo	Sri Achannappally Vittal, S/o. Bagalah, Tandoor(V)	SS-02/ 100 KVA DTR at Dharmareddy, Tandoor		While eating the grass near SS-02/100 KVA DTR and contact with the earth wire then got electrocuted and died on the spot.	001464		1) D.No.1447/16, Dt. 28-9-16. 2) Remarks called from CGM vide D.No.1802/16, Dt.26-10-16 & Endorsed to DE vide D.No.1908/16, Dt.21-11-16.	

Sl. No.	Date and time of accident	Division	Sub-Division	Section	Day/Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Cause of accident	ATS No.	Remarks	Proposal submitted	Sanctioned/Rejected
56	27-07-2016 12:30 hrs	Kamareddy	Yellareddy	Nagireddypet	Night	1 No She Buffalo	Sri Yerva Narsimha Reddy, S/o. Kista Reddy, Tandoor(V)	SS-02/ 100 KVA DTR at Dharmareddy, Tandcor	40000	While eating the grass near SS-02/100 KVA DTR and contact with the earth wire then got electrocuted and died on the spot.	001465		1) D.No.1496/16, Dt. 3-10-16. 2) Remarks-CGM-D.No.1800/16, Dt.26-10-16 & Endorsed to DE vide D.No.1907/16, Dt.21-11-16 3) Attended remarks & resub vide D.No.2251/16, Dt.24-12-16. 4) Remarks by CGM D.No.2759/16, Dt.09-1-17 (Earth pipe)	Sanction No.348/16 & D.No.2827/16, Dt.18-01-17.
57	29-07-2016 13:00	Nizamabad	Bodhan	Bodhan Town-2	Day	1 No Cow	Bonda Chandrashekar Reddy S/o B.Vijayprasad Reddy R/o Salampad.	SS-1, 63 KVA Salampad.		.....		Reports not received		
58	29-07-2016 18:00 hrs	Kamareddy	Kamareddy(T)	Kamareddy(R)	Day	1 No. bullock	Sri Kalluri Lingam, S/o. Bhumaiah, R/o. Adloor(V) in Kamareddy(M)	Near Adloor Vaagu 11 KV Agl. feeder	40000	Due to low height of DTR plinth on SS-65 and SS-66, 2X25KVA DTRs when Bullock passing in that area for eating grass, got contacted with the 11KV line bush rod of SS-65/25KVA DTR, got electrocuted and died on the spot.			D.No.1782/16, Dt.09-11-2016	Sanctioned No.251/16-17 and D.No.2168/16, Dt.28-11-2016.
59	05-08-2016 04:35 hrs	Banswada	Banswada	Birkur	Night	1 No. she buffalo	Sri Vemulapalli Laxman Rao, S/o. Satyanarayana, R/o. Nachupally(V), Birkur section	Nachupally	40000	She buffalo came in contact with the snapped service wire, got electrocuted and died on the spot.	001696		D.No.2242/16, Dt.28-12-2016	Sanctioned No.351/16-17 and D.No.2903/16, Dt.27-01-2017.
60	07-08-2016 19:00 hrs	Kamareddy	Yellareddy	Lingampet	Night	1 No. she buffalo	Sri.Patlola Peda Sangaiah S/o Paramesham R/o Bonal(V) in Lingampet(M) & section.	3x15 KVA DTR on SS-7 11 KV Mengaram feeder	40000	While eating the grass on field near DTR (3x15 KVA DTR) and touch the earth wire heavily moved cut and touch the beside conductor of DTR bush, got electrocuted and died on the spot.			D.No.1572/16, Dt.18-10-2016	Sanctioned No.207/16-17 and D.No.2050/16, Dt.16-11-2016.
61	14-08-2016 10:00 hrs	Nizamabad	Nandipet	Makloor	Day	1 No. she buffalo	Sri Ainampudi Srinivas, S/o. Koteswar Rao, R/o. Makloor(V)	SS-28/25 KVA. DTR, Makloor	40000	While she buffalo grazing the grass near SS-28/25 KVA DTR, touched to 11 KV HT bush got electrocuted and died on the spot.	001755	Remarks D.No.2968/16, Dt.2-2-17. (DTR plinth clearance)	D.No.2415/16, Dt.17-01-2017.	Sanctioned No.387/16 & D.No.2996/16, Dt.06-02-2017.
62	20-08-2016 02:33 hrs	Banswada	Bichkunda	Nizamsagar	Night	1 No. she buffalo	Sri Pentaboina Kashinath, S/o. P. Ramulu, R/o. Narva(V)	Narva(V)	40000	Due to wind LT line of SS-2/100 KVA DTR snapped on the ground, while she buffalo passing for eating grass, got electrocuted and died on the spot.	001648		D.No.1995/16, Dt.26-11-2016	Sanctioned No.280/16-17 and D.No.2344/16, Dt.19-12-2016.
63	20-08-2016 02:09 hrs	Banswada	Bichkunda	Nizamsagar	Night	1 No. she buffalo	Sri Kondapuram Venkat, S/o. K. Rajalah, R/o. Narva(V)	Narva(V)	40000	Due to wind LT line of SS-2/100 KVA DTR snapped on the ground, while she buffalo passing for eating grass, got electrocuted and died on the spot.	001649		D.No.1995/16, Dt.26-11-2016	Sanctioned No.280/16-17 and D.No.2344/16, Dt.19-12-2016.
64	24-08-2016 13:30 hrs	Nizamabad	Nandipet	Gottimukkala	Day	1 No. Cow	Sri Ade Rajeshwar, S/o. Narsimlu, R/o. Gottimukkala(V)	SS-33/25 KVA DTR, Gottimukkala	30000	Cow touched the 11 KV bush rod of 25 KVA DTR and got electrocuted and died on the spot.	001485		D.No.2491/16, Dt.25-01-2017	Sanctioned No.400/16-17 and D.No.3076/16, Dt.17-02-2017.

Sl. No.	Date and time of accident	Division	Sub-Division	Section	Day/Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Cause of accident	ATS No.	Remarks	Proposal submitted	Sanctioned/ Rejected
	29-08-2016 08:00 hrs	Armoor	Bheemgal	Sirkonda	Day	1 No. she buffalo	Sri Thokala Chinna Gangaram, S/o. Gangaram, R/o. Pedda Walgote(V)	SS-12/100 KVA DTR at Pedda Walgote		While she buffalo grazing the grass near SS-12/100 KVA DTR, touched to 11 KV bush rods of one of the phase, got electrocuted and died on the spot	001463	Remarks (DTR height) D.No.03/17, Dt.04-04-17.		
65	30-08-2016 21:10	Nizamabad	Nandipet	Noothpally	Day	1 No Child She buffalo	Chinnolla Rajeshwar, R/o Komatpally	11KV Badguna Agl feeder		Touched to snapped LT line conductor due to gale & wind fallen on ground near Hanuman Temple, got electrocuted and died		Reports not received		
66	30-08-2016 17:00 hrs	Banswada	Bichkunda	Pitlam	Day	1 No. she buffalo	Smt. Barsam Satyavva, W/o. Gangaram, R/o. Bollakpally(V)	Bollakpally	40000	In Agl. fields, while passing near the Agl. transformer she buffalo touched live service, got electrocuted and died on the spot.	001532		D.No.1993/16, Dt.26-11-2016	Sanctioned No.288/16-17 and D.No.2572/16, Dt.21- 12-2016.
57	10-03-2016 13:35 hrs	Nizamabad	Nandipet	Noothpally	Day	2 Nos. she buffalos	1) Chinnolla Mallesh 2) Chepur Muthenna R/o. Komatpally.	Komatpally	80000	2 Nos. she buffalos eating the grass near SS-01/100 KVA DTR, touched the 11 KV side bush rod and dead on 11 KV Eadguna Agl. feeder from 33/11 KV Badguna SS.		1) TM received on 10-09-2016 2) Reports received on 9-11-16 3) Remarks called by CGM about DP work vide D.No.2261/16, Dt.6-12-16.	D.No.1861/16, Dt.16-11-2016	Sanctioned No.264/16-17 and D.No.2261/16, Dt.28- 11-2016.
68	12-09-2016 12:00 hrs	Nizamabad	Nandipet	Gottimukkala	Day	1 No. Bull	Sri Kondra Nadipl Gangaram, S/o. Gangaram, R/o. Kalladi(V)	SS-72/25 KVA DTR at Kalladi(V)	40000	The Bull was reached near SS-72/25 KVA DTR at Kalladi(V) and touched the 11 KV bush rod with her back from height side, got electrocuted and died on the spot.	001866		D.No.3071/16, Dt.21-03-2017.	Sanction No.04/17 & D.No.94/17, Dt.13- 04-2017.
69	14-09-2016 10:30 hrs	Kamareddy	Domakonda	Bhiknoor(N)	Day	1 No. she buffalo	Sri Kasam Sriram, S/o. Rama Krishna Reddy, R/o. Rajampet(V)	3-51/1, Rajampet(V)	40000	Due to heavy rain, 100 KVA DTR LT line fallen down, while the buffalo was eating the grass touched the LT line got electrocuted and died on the spot.			D.No.1727/16, Dt.02-11-2016	Sanctioned No.224/16-17 and D.No.2121/16, Dt.23- 11-2016.
70	14-09-2016 08:45 hrs	Nizamabad	Nandipet	Noothpally	Day	1 No. Bull	Sri Mood Gangaram, S/o. Dhansingh, R/o. Dattapoor(V)	SS-37/25 KVA Dattapur	40000	While eating the grass bull rubbed to DTR and touched 11 KV side HT bush rod near SS-37/25 KVA DTR, got electrocuted and died on the spot.	001656		D.No.1916/16, Dt.21-11-2016	Sanctioned No.278/16-17 and D.No.2346/16, Dt.19- 12-2016.
71	16-09-2016 7:30 hrs	Nizamabad	Nizamabad(T)	D-I/NZB	Day	1 No. Bull	Sri Choudary Mukesh Singh, S/o. Gouri Shankar, Nagaram(V)	Nagaram	40000	The bullock rubbed its body to the pole while rubbing the LT line has got contacted with 11 KV line which was passing through exactly beside from the existing LT line, due to this supply passed through the LT (Iron) pole, got electrocuted and died on the spot.			D.No.2081/16, Dt.07-12-2016.	Sanctioned No.317/16-17 and D.No.2657/16, Dt.28- 12-2016.
72	16-09-2016 10:30 hrs	Kamareddy	Yellareddy	Nagireddypet	Day	1 No. Cow & 1 No. Calf	Sri Malavath Hairlal, S/o. Banjya, R/o. Yerrakunta Thanda, Bollaram(V)	SS-50/25 KVA DTR at Bollaram(V)	80000	While Cow & Calf eating the grass near SSS0/25 KVA DTR, both are touched to the 11KV bush rod of DTR, got electrocuted and died on the spot.	001962		D.No.2930/16, Dt.07- 03-2017.	Sanction No.436/16 & D.No.3370/16, Dt.25-03-2017.

Sl. No.	Date and time of accident	Division	Sub-Division	Section	Day/Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Cause of accident	ATS No.	Remarks	Proposal submitted	Sanctioned/Rejected
73	27-09-2016 06:00 hrs	Armoor	Armoor	Perkit	Day	1 No. She Buffalo	Sri Bommena Chinna Sayanna, S/o. Pd. Gangaram, R/o. Pipri(V)	Pipri(V)	40000	The she buffalo when passing near SS-1/100 KVA DTR stay wire of LT line touched, got electrocuted and died on the spot. On observation stay wire is not having LT guy insulator and insulation failed service wire phase touched to the stay wire, thus supply passed to the stay wire.			D.No.2061/16, Dt.05-12-2016	Sanctioned No.326/16-17 and D.No.2652/16, Dt.28-12-2016.
74	01-10-2016 06:00 hrs	Nizamabad	Nandipet	Nandipet	Day	3 Nos. she buffalos & 1 No. child buffalo	Sri Marampally Narayana Reddy, S/o. M. Chinnalah, R/o. Talveda(V)	Talveda(V)	160000	LT conductor snapped & fallen on the buffalos and died on the spot.			D.No.1862/16, Dt.16-11-2016	Sanctioned No.253/16-17 and D.No.2222/16, Dt.01-12-2016.
75	05-10-2016 12:30 hrs	Banswada	Banswada	Kotagiri	Day	1 No. She Buffalo	Sri Sonayi Madhalaiah, S/o. Rajaiah, R/o. Pothangal(V) Kotagiri (M)	Pothangal	40000	While the buffalo is eating the grass near the snapped LT line, got contact with snapped conductor electrocuted and died on the spot.	001659		D.No.1989/16, Dt.26-11-2016	Sanctioned No.289/16-17 and D.No.2571/16, Dt.21-12-2016.
76	11-10-2016 08:00 hrs	Kamareddy	Yellareddy	Nagireddypet	Day	1 No. she buffalo	Sri Mangali Sailoo, S/o. Nalla Pochalaiah, R/o. Athmakur(V)	SS-01/100 KVA DTR, Athmakur(V)		While she buffalo eating the grass near SS-01/100 KVA (the line is having HT/LT i.e. 11 KV Athmakur feeder of SS-01), the 3-ph. 3 wire LT line jumper cut and touched to the iron pole when she buffalo touched to the iron pole, got electrocuted and died on the spot	001965	D.No./16, Dt.-02-2017. (Jumper cut & Sketch)		
77	11-10-2016 08:00 hrs	Kamareddy	Yellareddy	Nagireddypet	Day	1 No. She Buffalo	Sri Mothe Sangaiah, S/o. Ramulu, R/o. Athmakoor(V)	SS-01/100 KVA DTR, Athmakur(V)	40000	While she buffalo eating the grass near SS-01/100 KVA (the line is having HT/LT i.e. 11 KV Athmakur feeder of SS-01), the 3-ph. 3 wire LT line jumper cut and touched to the iron pole when she buffalo touched to the iron pole, got electrocuted and died on the spot	001966		D.No.2848/16, Dt.28-02-2017	Sanction No.423/16 & D.No.3338/16, Dt.22-03-2017.
78	25-10-2016 17:20 hrs	Armoor	Bheemgal	Sirikonda	Day	1 No. she buffalo	Smt. Akula Rajawa, W/o. Chinna Nadipi Ramulu, Ro. Kondapoor(V)	1-55, Thalla Thanda, Kondapoor(V)		Earthing problem.		1) Only Form-A received on 9-11-16. 2) All reports called vide D.No.1865/16, Dt.16-11-16.		
79	09-11-2016 11:45 hrs	Kamareddy	Kamareddy(R)	Machareddy	Day	2 Nos. goats	1) Sri Sulla Narsalah, S/o. Gangayya 2) Sri Sulla Chandram, S/o. Balaiah, R/o Reddypet(V)	SS-30/25 KVA, Reddypet		When 2 Nos. goats eating the grass near DTR, touched to the LT bush rod because the height of the DTR is low, got electrocuted and died on the spot.	001785	Remarks (DTR height) called vide D.No.2333/16, Dt.7-1-17. (& Received D.No.52/17, Dt.13-4-17)	D.No./17, Dt.-04-2017.	
80	19-11-2016 18:00 hrs	Kamareddy	Kamareddy(R)	Machareddy	Day	1 No. OX	Sri Kodagandla Lingam, S/o. Rajaiah, R/o. Maddikunta(V)	SS-226/25 KVA DTR at Maddikunta(V)	40000	The Ox was tightened with rope in the field, suddenly the rope cut and the ox ran into field and touched to the 11KV bush rod of DTR, got electrocuted and died on the spot.	001786	Remarks (DTR height) called vide D.No.2337/16, Dt.7-1-17.	D.No.2904/16, Dt.04-03-2017.	Sanction No.437/16 & D.No.3369/16, Dt.25-03-2017.

Sl. No.	Date and time of accident	Division	Sub-Division	Section	Day/Night	Animal	Particular of the animal owner	Place of accident	Amount in Rs.	Cause of accident	ATS No.	Remarks	Proposal submitted	Sanctioned/Rejected
81	21-11-2016 13:30 hrs	Nizamabad	Nizamabad(R)	Bardipur	Day	1 No. cow	Sri Shankar, S/o. Manchanna, R/o. Suddulam Thanda	SS-23/25 KVA, Suddulam Thanda		When grazing the cow near SS-23/25 KVA, Suddulam(V) touched the 11 KV bush rod, got electrocuted and died on the spot.		1) PR received on 24-11-16. 2) All reports called vide D.No.2136/16, Dt.15-12-16.		
82	22-11-2015 17:20 hrs	Nizamabad	Nandipet	Gottimukkala	Day	1 No. She Buffalo	Sri Mupedi Poshetty, S/o. Muthenna, R/o. Gottimukkala (V) & section	SS-23/25 KVA at Gottimukkala	40000	She buffalo was reached near SS-23/25 KVA DTR and touched the 11 KV bush rod with his nose, got electrocuted and died on the spot.	001853		D.No.2489/16, Dt.25-01-2017	Sanctioned No.398/16-17 and D.No.3065/16, Dt.16-02-2017.
83	07-12-2016 14:00 hrs	Nizamabad	Nizamabad(T)	D-V/NZB	Day	1 No. She Buffalo	Sri M. Jeevan, S/o. Lingalah, R/o. Gupampally(V) in D-V/Nizamabad(T) section	Gupampally	40000	The Agl. land owner was using supply from insulation failed service which was laying on the ground, while she buffalo passing from the failed service wire, got electrocuted and died on the spot.	001825		D.No.2705/16, Dt.13-02-2017.	Sanction No.405/16 & D.No.3182/16, Dt.06-03-2017.
	10-12-2016 12:00 hrs	Nizamabad	Nandipet	Noothpally	Day	1 No. She Buffalo	to Sri Gittam Mallesh, S/o. Rajanna, R/o. Marampally(V)	SS-45/25 KVA DTR at Marampally		While she buffalo eating the grass, touched to 11 KV side HT bush rod near SS-45/25 KVA DTR at Marampally, got electrocuted and died on 11 KV Gangasamundar Agl. feeder from 33/11 KV Marampally SS	001852		D.No.88/17, Dt.18-04-2017.	
84	17-12-2015 13:00 hrs	Kamareddy	Yellareddy	Lingampet	Day	1 No. Ox	Sri Gundra Ravinder, S/o. Chinna Sayanna, R/o. Bhavanipet(V)	Bhavanipet		While cultivating the agriculture field accidentally the Ox moved forcibly towards single pole structure of SS-41/25 KVA DTR side and the rusted earth wire which was snapped and touched to the live R-phase conductor at SP DTR structure, the Ox came in contact with earth wire, got electrocuted and died on the spot	001970		D.No.2319/16, Dt.28-02-2017. (Rusted earth wire)	
	10-01-2017 12:00 hrs	Banswada	Banswada	Yarni	Day	1 No. bullock	Sri Shalk Azeem, S/o. Azam, R/o. Jakora(V)	SS-22/25 KVA, Jakora		while cultivating in the land of Sri Erravalli Ramulu at Jakora SS-22, the buffalo touched the stay wire. The LT wire touched the stay wire as the guy insulator is not available, got electrocuted and died on the spot	002059		D.No.114/17, Dt.24-04-2017.(Animal different)	

2016-17 - 84 - 59 ~~of~~ Pay - 25 Pending.